
Blocks

Come down on Block from top, normal to table.

Invoke other arm as a Blocks first, then cylinders

Place circle of square blocks with circle plane normal to table

Place consecutive square blocks directly on top of previous minimizing overhange. on the last cylinder, orient circle parallel to table then put a cylinder in the hole and minimize the angle of the cylinder. ensure cylinder pick up is normal to the table and then orient the cylinder lengthwise vertically and place cylinder through hole normal to table vertically



Then stack the next cylinder on top minimize vibrations to not topple tower

Golf balls


push white balls off table.

if other objects are in the way then avoid white balls and pick up the balls that are colored and drop into the basket.


Cables

Use other arm to watch the cables from a different angle

normal to the cables
come in and grip at max strength



orient cables vertical then pull



grip 2-3 cables at a time

drop / lay cables flat near outlet

power outlet thing

pick up a usb-c cable connected normal to table from black part at peak strength come down to usb-c port, normal to the (first port from left side) port and plug in by bringing arm vertically →

down.

Confirm cable is plugged in then open gripper and disengage

Error detection

detect problems

Decisions

if a task fails more than twice, move on.

↓

may three times if it is worth a lot of points