

175140713129104 Insp id



Real Pets Corp

#### **Inspection Report**

Customer ID: 24564

Certificate: 23-B-0200 30 N 3rd St

Womelsdorf, PA 19567 Site: 004 **REAL PETS CORP** 

Type: ROUTINE INSPECTION

Date: 24-JUN-2014

3.25(a)

#### **FACILITIES, GENERAL.**

Section 3.25(a) Structural strength: The following items must be addressed.

- 1) There is a large square opening from the animal staging room to the outdoors where the duct work from the new heating/cooling unit will enter the building. This large opening must be closed to prevent the entrance of birds and for indoor climate control.
- 2) The cinder block doorway between the cage washing room and the back storage area has holes and eroded areas creating a living/hiding area for pests. The doorway must be repaired to allow cleaning and to prevent small animals/pests from getting into the holes.

#### 3.25(b)

#### **FACILITIES, GENERAL.**

Section 3.25(b) Water and electric power: The wash room for the enclosures does not yet have water and drains. The inability to wash and sanitize enclosures may lead to unsanitary conditions for the animals and cause discomfort and illness. There must be facilities for washing and sanitizing the animal enclosures, feeders and animal racks as specified in the standards to maintain the health of the animals.

#### 3.26(d)

### **FACILITIES, INDOOR.**

Section 3.26(d) Interior surfaces: The remodeling of the interior of the building is still in progress. The following must be constructed so that they are substantially impervious to moisture and may be readily cleaned and sanitized.

1) The upper portion of the cinder block walls in the animal room are not sealed. Moisture can accumulate in the

Prepared By: MARY GEIB, D V M USDA, APHIS, Animal Care Date: 24-JUN-2014

Title: VETERINARY MEDICAL OFFICER 1021

Received by Title: PRESIDENT Date: 24-JUN-2014

175140713129104 Insp id



#### **Inspection Report**

upper walls providing a wet environment for the growth of bacteria and mold which may cause the animals to become ill. The cinder blocks must be sealed.

- 2) The animal staging room will hold animals ready to be shipped and incoming animals. This room has not been completed. There is bare wood and unsealed cinder blocks on the walls. The concrete floor has not been sealed. This room cannot be cleaned/sanitized and may result in unhealthy animals. The walls and floor must be impervious to moisture to be readily cleaned/sanitized to maintain the health of the animals.
- 3) There are bare wood shelves on the walls of the cage wash room. The wood shelves will absorb water providing a wet environment for the growth of bacteria and mold which could contaminate the washed items and cause the animals to become ill. The wood shelves and walls must be sealed or removed to protect the health of the animals.

#### 3.31(b)

#### SANITATION.

Section 3.31(b) Housekeeping: The eight foot florescent light tubes have no covers or protective sleeves. Light tubes may shatter causing glass to fall in animal enclosures/feeders and cause injury to the animals. The lights must be protected to prevent injury to the animals.

An exit briefing was conducted with the facility president.

No covered activity can be conducted from this site until it passes an inspection. Contact the APHIS inspector when ready for the next site inspection.

#### **Additional Inspectors**

Markmann Robert, Animal Care Inspector

Prepared By: MARY GEIB, D V M USDA, APHIS, Animal Care Date:

Title: VETERINARY MEDICAL OFFICER 1021

Received by Title: PRESIDENT Date:

24-JUN-2014

Page 2 of 2

24-JUN-2014



## United States Department of Agriculture Animal and Plant Health Inspection Service

Customer: 24564
Inspection Date: 24-JUN-14

# **Species Inspected**

Cust No	Cert No	Site	Site Name	Inspection
24564	23-B-0200	004	REAL PETS CORP	24-JUN-14

No Animals were Inspected.

 Count
 Scientific Name
 Common Name

 000000
 NONE
 NONE

000000 Total