

Summit Ridge Casualty

CLAIM INSPECTION REPORT

Claim and Adjuster Information

Claim Number	CLM-901710
Policy Number	HO-2026-40237
Named Insured	Marcus T. Okonkwo
Loss Location	2217 Sycamore Court, Lakeside, OH 44311
Date of Loss	05/18/2026
Date of Inspection	05/28/2026
Peril	Water damage (plumbing)
Assigned Adjuster	Brian K. Larson · License TX-CLM-48921
Adjuster Phone	(972) 555-0266

Summary

Upon arrival, the kitchen and dining room showed evidence of extensive water intrusion from a failed 3/8-inch compression supply line beneath the kitchen sink. Water spread beneath the laminate flooring and wicked into the lower cabinetry and adjacent drywall. Moisture readings of 18-24% were recorded in affected areas. Emergency drying equipment has been placed by a restoration contractor. The damage is consistent with the insured's report and is covered under the policy.

Site Inspection Findings

A physical inspection of the loss site was conducted on the date noted above. Photographs and measurements were taken and are retained in the claim file. All findings are consistent with the reported cause of loss.

Cause of Loss Determination

Cause of loss determined to be: **Water damage (plumbing)**. The loss is covered under the terms of the policy subject to applicable deductibles and any sublimits noted in the declarations or attached endorsements.

Damage Assessment and Estimate

Line Item	Estimated Cost
Laminate flooring removal and replacement (320 sq ft)	\$3,840.00
Lower cabinet replacement — kitchen (6 linear ft)	\$1,920.00
Drywall repair and paint — kitchen and dining room	\$1,250.00
Plumbing supply line replacement	\$380.00
Moisture mitigation and drying services	\$1,100.00
General contractor overhead and profit (15%)	\$1,274.00

	Amount
TOTAL ESTIMATED REPLACEMENT COST VALUE	\$9,764.00
Less: Policy Deductible	(to be applied at payment)
Applicable Depreciation (if ACV basis)	(to be calculated)
RECOMMENDED INITIAL RESERVE	\$10,252.20

Recommended Reserve

Based on the field inspection and line-item estimate, an initial reserve of \$10,252.20 is recommended (replacement cost value plus 5% contingency). The reserve may be revised pending contractor bids, supplemental documentation, or identification of additional covered damages.

Report prepared by: Brian K. Larson, Licensed Property Adjuster (TX-CLM-48921). This report is for internal claims use only and does not constitute an admission of liability or a final coverage determination.