










12v input connector




TERMINAL BLOCK TO CHAdemo SIGNAL CONNECTOR



MONITOR SS1 AND SS2  
SS1 MONITORS FROM SS1 TO FG  
SS2 MONITORS FROM SS1 TO SS2



WE DO NOT DRIVE CONTACTORS DIRECTLY  
INSTEAD THEY ARE DONE VIA SOFTWARE AND THIS DRIVER



CONTACTOR +12V CONNECTOR

