



RAILROAD COMMISSION OF TEXAS

Form H-5

1701 N. Congress
P.O. Box 12967
Austin, Texas 78701-2967

UIC No.: 000031928
Filing No.: 46780
Submittal Date: 02/27/2023
Version: 1
Evaluation: 03/21/2023
Test Status: Inconclusive

DISPOSAL/INJECTION WELL PRESSURE TEST REPORT - Page 1 of 2

PREPARER INFORMATION

Preparer: Billie Grewing Phone: 940-759-4949
E-mail: mdcinc@ntin.net

OPERATOR INFORMATION

Operator Name: 6 HESS, LLC Operator: 953808
Address Line 1: PO BOX 53 City: MUENSTER
Address Line 2:
State: TX Postal Code: 76252

LEASE AND WELL

API: 09731455 Injection Well: Enhanced Recovery
District: 09 Lease: 02166 Well No.: 11
Lease: DANGLEMEYER Field Number: 20350001
Field Name: COOKE COUNTY REGULAR
County: COOKE

TEST REPORT INFORMATION

Reason for: 5-Year Test as Required by Statewide Rule Date Test Performed: 02/01/2023
Retest: No For a Retest, Date of Previous Test:
Remedial Actions
Prior to

WELL COMPLETION

	Casing/Tubing Size	Depth Set (ft.)	Top Of Cement
Long String Casing	4 1/2	884	884
Tubing or Hanging String	2	800	

Packer Make/Model: Packer - Johnson Tension

Depth Packer: 800 ☐ No Packer / Injection Down Casing



RAILROAD COMMISSION OF TEXAS

Form H-5

1701 N. Congress
P.O. Box 12967
Austin, Texas 78701-2967

UIC No.: 000031928
Filing No.: 46780
Submittal Date: 02/27/2023
Version: 1
Evaluation: 03/21/2023
Test Status: Inconclusive

DISPOSAL/INJECTION WELL PRESSURE TEST REPORT - Page 2 of 2

INJECTION INTERVALS AND TEST PRESSURES

	Top	Bottom	
Permitted Injection	825	838	
Completed Injection	820	830	☐ No Completed Intervals
Authorized Liquid Injection	900		
Authorized Gas Injection			Well Status: Shut-In

TEST PRESSURES AND OTHER INFORMATION

☐ Well did not pressure up. No test pressures to report. ☒ Digital Recorder readings are attached to filing.

	Tubing or Hanging String	Casing	Surface Casing
INITIAL	660	660	
After 15 minutes	660	660	
After 30 minutes	660	660	

Test Witnessed by RRC: No Name of RRC

Injection Fluid Description:

Annulus Fluid Description: Liqui Salt Water

Other Tests/Surveys Performed on
this Well:

Operator Comments On Test: