


Revision 09.01.19



Controls

- Fuzz
- Tone
- Level


All trademarks and registered trademarks are the property of their respective owners. The company, product, and service names used in this web site are for identification purposes only. Use of these names, logos, and brands does not imply endorsement.



Scythe Fuzz Parts List

RESISTORS (1/4W)		CAPACITORS		TRANSISTORS	
R1	1M	C1	100p	Q1	MPSA18
R2	47K	C2	1u	Q2	AC176
R3	330R	C3	47p		
R4	470K	C4	10u	DIOD	ES
R5	10K	C5	1u	D1	1N4148
R6	10K	C6	1u	D100	1N5817
R7	1K	C7	22u		
R8	1K	C8	10n	POTENTIOMETERS	
R9	10K	C9	470p	FUZZ	B250K
R10	33K	C10	1u	LEVE	L A100K
R11	33K	C100	100u	TONE	B100K
R100	4K7				







Scythe Fuzz

Wiring Diagram





Scythe Fuzz Drill Template 125B enclosure with top mounted jacks

