


Revision 05.04.20



Controls

- Drive
- Volume




OctaMayer Octave Fuzz Parts List

| RESISTORS (1/4W) | | |
|------------------|------|--|
| R1 | 2M2 | |
| R2 | 680K | |
| R3 | 820K | |
| R4 | 100K | |
| R5 | 220R | |
| R6 | 39K | |
| R7 | 39K | |
| R8 | 220R | |
| R9 | 47K | |
| R10 | 330K | |
| R11 | 470K | |
| R12 | 10K | |
| R13 | 10K | |
| R14 | 2M2 | |
| R15 | 820K | |
| R16 | 100K | |
| R17 | 2M2 | |
| R18 | 2M2 | |
| R19 | 10K | |
| R20 | 150K | |
| R100 | 4K7 | |
| R101 | 180K | |

| CAPACITORS TRANSISTORS | | RS | |
|------------------------|------|----------------|--------|
| C1 | 10n | Q1 | 2N3906 |
| C2 | 470p | Q2 | MPSA13 |
| C3 | 1n | Q3 | MPSA13 |
| C4 | 100n | Q4 | MPSA13 |
| C5 | 22u | | |
| C6 | 10n | DIODES | |
| C7 | 22u | D1 | 1N4148 |
| C8 | 22u | D2 | 1N4148 |
| C9 | 10n | D100 | 1N5817 |
| C10 | 10n | | |
| C11 | 100n | POTENTIOMETERS | |
| C101 | 22u | DRIVE | C10K |
| | | VOLUME | A1M |
| | | | |

OctaMayer Octave Fuzz PedalPCB





OctaMayer Octave Fuzz

Wiring Diagram





OctaMayer Octave Fuzz Drill Template 125B Enclosure

