


Revision 01.31.19



Controls

- Gain
- Level
- Bass
- Treble
- Character (Toggle switch) (Fat/Clean/Mids)

All trademarks and registered trademarks are the property of their respective owners. The company, product, and service names used in this web site are for identification purposes only. Use of these names, logos, and brands does not imply endorsement.



Parts List

RESIS	TORS	(1/4W)
D 1	17.7	

RESISTORS (1/4W)		
R1	1M	
R2	4K3	
R3	10K2	
R4	10K	
R5	47K	
R6	100K	
R7	100K	
R8	10K	
R9	1M	
R10	1M	
R11	3K9	
R12	3K9	
R13	22K	
R14	100K	
R15	10K	
R16	1K	
R17	47K	
R18	4K7	
R19	4K7	
R20	3K3	
R21	15K	
R22	1K	
R23	15K	
R24	3K3	
R25	100K	
R26	100R	
R100	4K7	
R101	100K	
R102	100K	

CAPACITORS		
C1	100n	
C2	1n	
C3	4u7	
C4	1n	
C5	100n	
C6	10n	
C7	220n	
C8	100n	
C9	1u	
C10	1n	
C11	1u	
C12	220n	
C13	1n	
C14	1u	
C15	10u	
C16	8n2	
C17	47n	
C18	47n	
C19	1n	
C20	10u	
C21	100n	
C100	220u	
C101	10u	

INTEGRATED CIRCUITS

IC1	OPA2134
IC2	OPA2134
IC3	OPA2134

DIODES


D1	1N914
D2	1N914
D3	1N914
D4	1N914
D5	1N914
D6	1N914
D100	1N5817

POTENTIOMETERS

LEVEL	B10K
GAIN	C100K
TREBLE	B50K
BASS	B50K


SWITCHES

SPDT (On/Off/On) SW1





Wiring Diagram





Drill Template 125B enclosure with top mounted jacks

