


Revision 12.16.18



Controls

- Level
- Gain
- Bloom
- Starve

All trademarks and registered trademarks are the property of their respective owners. The company, product, and service names used in this web site are for identification purposes only. Use of these names, logos, and brands does not imply endorsement.



R100 4K7

Plecostomus Fuzz


Parts List


RESISTORS (1/4W)		CAPACITORS	TRANSISTORS
R1	1K	C1 470p	Q1 2N5089
R2	1M	C2 100n	Q2 2N5089
R3	2M2	C3 100n	
R4	1K	C4 2u2	DIODES
R4 R5	1K 47K	C4 2u2 C5 100n	DIODES D100 1N5817

POTENTIOMETERS

LEVEL	A100K
GAIN	B500K
BLOOM	A100K
STARVE	A100K










Plecostomus Fuzz

Wiring Diagram





Plecostomus Fuzz
Drill Template
125B enclosure with top mounted jacks

