


Revision 11.08.19




## **Controls**

None!



## Propolis Fuzz Parts List


RESISTORS (1/4W)		CAPACITORS		TRANSISTORS	
R1	1M	C1	10u	Q1	2N2222
R2	22K	C2	2n2	Q2	2N2222
R3	10K	C3	100n	Q3	2N2222
R4	100K	C4	1u	Q4	2N2222
R5	1K8	C5	1u		
R6	47K	C6	10u	DIODES	
R7	10K	C7	10u	D1	1N4007
R8	10K	C8	2u2	D2	1N4007
R9	10K	C9	ln	D3	1N4007
R10	100K	C10	22n	D4	1N4007
R11	10K	C100	100u	D100	1N5817
R12	1K8				
R13	100K				
R14	10K				
R15	100K				
R16	42K				
R17	330K				
R100	4K7				





## **Propolis Fuzz**

Wiring Diagram





## Propolis Fuzz Drill Template 125B Enclosure

