


Dirt Dauber Sub-Octave Fuzz

Revised 8/18/22



CONTROLS

FOOTSWITCHES

- Octave
- Fuzz
- Level
- Octave -1 / -2 (Toggle Switch)
- Active/Bypass
- Octave

All trademarks and registered trademarks are the property of their respective owners. The company, product, and service names used in this web site are for identification purposes only. Use of these names, logos, and brands does not imply endorsement.



PedalPCB Dirt Dauber Sub-Octave Fuzz


Parts List (Page 1 of 1)

LOCATION	VALUE	TYPE	NOTES
R1	2K2	Resistor, 1/4W	
R2	3M3	Resistor, 1/4W	
R3	3M3	Resistor, 1/4W	
R4	100K	Resistor, 1/4W	
R5	100K	Resistor, 1/4W	
R100	4K7	Resistor, 1/4W	
R101	4K7	Resistor, 1/4W	
<u> - -</u>	1137	1 (00.000), 17 177	
C1	100n	Film capacitor, 7.2 x 2.5mm	
C2	1u	Electrolytic capacitor, 5mm	
C2 C3	100n	Film capacitor, 7.2 x 2.5mm	
C4	1u	Electrolytic capacitor, 5mm	
C100	100u	Electrolytic capacitor, 6.3mm	
C100	100u	Film capacitor, 7.2 x 2.5mm	
C101	100n	Film capacitor, 7.2 x 2.5mm	
C 102	10011		
D100	1N5817	Schottky diode, DO-41	
0100	TINGOTT	Scholiky diode, DO-41	
IC1	CD4049UBE	CMOS Hex/Buffer/Converter	
IC2	CD40490BE CD4040BE		
102	CD4040BE	CMOS 12-Bit Binary Counter	
CMA	ONI/ONI	Toggle quiteb CDDT	2 manition (ONI/ONI)
SW1	ON/ON	Toggle switch, SPDT	2-position (ON/ON)
OOTA)/E	D400K	10 many might an alla DOD manustrat	
OCTAVE	B100K	16mm right-angle PCB mount pot	
FUZZ	B100K	16mm right-angle PCB mount pot	
LEVEL	A100K	16mm right-angle PCB mount pot	
			+



Dirt Dauber Sub-Octave Fuzz


Schematic Diagram





PedalPCB Dirt Dauber Sub-Octave Fuzz

Wiring Diagram





PedalPCB Dirt Dauber Sub-Octave Fuzz

Drill Template

125B Enclosure

