



R12\_PWM\_D SERVO CH<sub>0</sub> 220 Ω R12\_PWM\_C SERV1 CH<sub>1</sub>  $220 \Omega$ R12\_PWM\_B 2WW/\_SERV2 CH<sub>2</sub> 220 Ω R12\_PWM\_SERV3 CH<sub>3</sub> 220 Ω R13\_PWM\_D 4WW\_5\_\_SERV4 CH4  $220 \Omega$ R13\_PWM\_C 3\_WW\_6 SERV5 CH<sub>5</sub>  $220 \Omega$ R13\_PWM\_B 2000 SERV6 CH<sub>6</sub>









## 17 DAVID J CUTTING

