



Enterprise House, Shenstone Drive, Aldridge, WS9 8TP
Tel: 01922 454687
Email: bookings@assuredlimited.co.uk

QUOTATION

Reference: 5 Kittoe Road, Sutton Coldfield, B74 4RY

Date of attendance: 7th November 2022

Quotation on behalf of: Chattings

Here is our initial quotation for works as requested. Please do not hesitate to contact us should you require any further information or wish to proceed.

Findings

The engineer attended to replace the boiler's expansion vessel and PRV. When testing the boiler, further problems presented. The engineer has advised that the electrodes are also faulty and to replace these the heat exchanger will need to be removed and so the graphite seal will need to be replaced. The display on the thermostat is faulty and only showing part of the screen so cannot be controlled.



Recommendation & Costing

Our recommendation is to supply and install both replacement electrodes and a graphite heat exchanger seal in the boiler, also replace wireless programmable thermostat.

COSTING – Materials £162.50, Labour £150.00, VAT £62.50

TOTAL - £375.00.

PLEASE NOTE, COSTS ARE VALID FOR 4 WEEKS, A FURTHER SURVEY MAY BE REQUIRED IF AUTHORISATION IS GIVEN AFTER 4 WEEKS HAVE ELAPSED.