






## Low Current



















Fix: Medir resistencia motor Medir inductancia motor Verificar si se añade símbolo motor DC

Add: Hierar