Lab 7 - Requirements analysis

Friday, April 17, 2020 11:34 AM

Hardware Requirements:

- MX7 Board
- LCD Display (PMOD)
- TMP3 Module (PMOD)
- RS-232 Module (PMOD)
- UART Cross-over cable
- 8 LED Module (PMOD)

I/O Requirements:

- Inputs:
 - o 3 Buttons on MX7
 - o TMP3 Temperature
- Outputs:
 - LCD Display
 - o Terminal
 - o 8 LEDs

Functional Requirements:

- 1. Select input power using 3 buttons individually or in combination range 0..7
- 2. Display output power level on LEDs and LCD display

LCD Displays: POWER LEVEL X

LEDs Display power level: 0..7 LED lit

- 3. Measure ambient temperature using TMP3 module convert to °F
- 4. Display temperature on terminal
- 5. If ambient temperature >= 80 °F
 - Flash message on LCD display Overheated
 - Transmit message to terminal Overheated follow with CR & LF
 - Turn off all LEDs, even if buttons are pressed
- 6. When ambient temperature lowers to < 80 °F, return to normal operation