8.3 Navigation and mapping

8.3.1 Tasks:

- 1. Stop the robot when it reaches the end of line.
- 2. Detecting the end of line can be done by measuring the time that robot spend over the black and white area. E.g. if the robot is driving along the line the time spent over black and time spent over white area will be quite the same. When line ends the robot will not detect the black area soon and the time spent over white area will increase significantly and that is the trigger for detecting the end of line.
- 3. Advanced: Make a function to align (move) the robot back to the line.

8.3.2 Questions:

- 1. How can we store a data to the controller's memory?
- 2. How can we measure time in programming loops?
- 3. What is the purpose of the prog. instr. exit(0);?

dr. David Rihtaršič

Program 1: Edn of Line Detection.

```
1
       #include "RobotMovingFunctions.h"
2
       const int LIGHT_SENSOR_PIN = A0;
       const int SURFACE_BRIGHTNESS_REFERENCE = 400;
3
       int time_on_black = 0;
4
5
       int time_on_white = 0;
6
       void setup()
7
8
       {
9
         setIOpins();
         pinMode(LIGHT_SENSOR_PIN , INPUT);
10
11
12
       void loop()
13
         int light_sensor_value = analogRead(LIGHT_SENSOR_PIN );
14
15
         if ( light_sensor_value < SURFACE_BRIGHTNESS_REFERENCE )</pre>
16
17
           // BLACK area
18
           moveLeft();
19
           time_on_white = 0; // reset time on white
20
           time_on_black++; // meas. time on black
           delay(100);
21
22
         }
23
         else
24
          // WHITE area
25
26
          moveRight();
27
           // Do similar meas.
           // of time on white
28
29
           delay(100);
30
           // If time is signif. longer:
31
           //
                     robotStop();exit(0);
32
         }
33
```

8.3.3 **Summary:**

8.3.3.1 <++>

8.3.4 Issues:

8.3.4.1 <++>

dr. David Rihtaršič