```
Main problems:
    78 "Improper Neutralization of Special Elements used in an OS Command
          ('OS Command Injection')"
https://cybersword.tech
                                 in www.linkedin.com/in/cybersword-tech
                                    @davidwowa
Oph1sher
```

Components:

Description:

Edimax IC-7100 does not properly neutralize requests. An attacker can

create specially crafted requests to achieve remote code

edimax ic-7100 firmware \*

execution on the device