CVE-2025-20633 - Score: 8.8

Components:

- mediatek mt7915 -
- mediatek mt7603 -
- mediatek mt7615 -
- mediatek software development kit *
- mediatek mt7622 -

Description:

In wlan AP driver, there is a possible out of bounds write due to an incorrect bounds check. This could lead to remote (proximal/adjacent) code execution with no additional execution privileges needed. User interaction is not needed for exploitation. Patch ID: WCNCR00400889; Issue ID: MSV-2491.

Main problems:

787 "Out-of-bounds Write"