## Components: netgear d6100 firmware netgear d6100 -

CVE-2016-10174 - Score: 9.8

## Description: The NETGEAR WNR2000v5 router contains a buffer overflow in the hidden

\\_lang\\_avi parameter when invoking the URL /apply.cgi?/lang\ \_check.html. This buffer overflow can be exploited by an unauthenticated attacker to achieve remote code execution. Main problems: 120 "Buffer Copy without Checking Size of Input ('Classic Buffer

♥ @davidwowa