```
Components:

draytek vigor2960 -
draytek vigor2960 firmware 1.3.1
```

CVE-2020-8515 - Score: 9.8

Description:

```
DrayTek Vigor2960 1.3.1\_Beta, Vigor3900 1.4.4\_Beta, and Vigor300B
```

```
1.3.3\_Beta, 1.4.2.1\_Beta, and 1.4.4\_Beta devices allow remote code execution as root (without authentication) via shell metacharacters to the cgi-bin/mainfunction.cgi URI. This issue has been fixed in Vigor3900/2960/300B v1.5.1.

Main problems:
```

```
78 "Improper Neutralization of Special Elements used in an OS Command
('OS Command Injection')"
```

