```
disclosure and/or arbitrary code execution.

Main problems:

125 "Out-of-bounds Read"
```

Description:

Out-of-bounds read vulnerability exists in Kostac PLC Programming Software (Former name: Koyo PLC Programming Software) Version 1.6.9.0 and earlier. The insufficient buffer size for the PLC program instructions leads to out-of-bounds read. As a result, opening a specially crafted project file may lead to information

NVD DB Update CVE-2023-22421 - Score: 7.8

jtekt kostac plc programming software \*

```
https://cybersword.tech
ph1sher
```

in www.linkedin.com/in/cybersword-tech