```
Description:

A vulnerability has been identified in RUGGEDCOM CROSSBOW (All versions < V5.5). The affected systems allow a privileged user
```

Components:

CVE-2024-27944 - Score: 7.2

versions < V5.5). The affected systems allow a privileged user to upload firmware files to the root installation directory of the system. By replacing specific files, an attacker could tamper specific files or even achieve remote code execution.

Main problems:

```
73 "External Control of File Name or Path"
```