```
mediatek mt6895tt -
 mediatek mt6835 -
mediatek mt6896 -
mediatek mt6895 -
 mediatek mt6886 -
 mediatek mt6813 -
 mediatek mt6897 -
 mediatek mt6878 -
mediatek mt6899 -
mediatek mt6835t -
mediatek mt6879 -
mediatek mt6980d -
mediatek nr16 -
mediatek nr17 -
 mediatek nr17r
 mediatek mt6878m -
                            Description:
In Modem, there is a possible out of bounds write due to a missing
     bounds check. This could lead to remote code execution, if a UE
     has connected to a rogue base station controlled by the attacker
     , with no additional execution privileges needed. User
```

interaction is not needed for exploitation. Patch ID:

Main problems:

♥ @davidwowa

in www.linkedin.com/in/cybersword-tech

MOLY01289384: Issue ID: MSV-2436.

787 "Out-of-bounds Write https://cybersword.tech

Oph1sher

NVD DB Update CVE-2025-20634 - Score: 9.8

mediatek mt6983 mediatek mt6980 mediatek mt2737 -