```
Main problems:
78 "Improper Neutralization of Special Elements used in an OS Command
      ('OS Command Injection')"
```

♥ @davidwowa

in www.linkedin.com/in/cybersword-tech

CVE-2022-46552 - Score: 8.8

Components:

Description:

D-Link DIR-846 Firmware FW100A53DBR was discovered to contain a
remote command execution (RCE) vulnerability via the lan(0)\

dlink dir-846 firmware 100a53dbr

dlink dir-846 -

https://cybersword.tech

Oph1sher