```
https://cybersword.tech
                               in www.linkedin.com/in/cybersword-tech
Oph1sher
                                 @davidwowa
```

Components:

Description:

Main problems:

Arris TG2482A firmware through 9.1.103GEM9 allow Remote Code Execution (RCE) via the ping utility feature.

commscope arris tg2482a -

-1 no CWE Description available