```
netgear d6100 firmware -
netgear d6100 -

Description:

The NETGEAR WNR2000v5 router contains a buffer overflow in the hidden
```

Components:

CVE-2016-10174 - Score: 9.8

_lang_avi parameter when invoking the URL /apply.cgi?/lang\ _check.html. This buffer overflow can be exploited by an unauthenticated attacker to achieve remote code execution.

Main problems:

```
Main problems:

120 "Buffer Copy without Checking Size of Input ('Classic Buffer
Overflow')"
```

