Open Issues List

Keeler Door w/ SecuRemote 2.0 07/31/15

\eerer	DU	or w/ SecuRemote 2.0						07/31/15
PRTY ABC	#	Issue Description	Status/Action Plan	Resp.	Open Date	Target Date	Update	Actual Comp
			Documentation					
	1	Users Manual needs to be updated	Who is responsible? Ashok last to update. 6/23 - Team reviewing	Ashok	06/22/15		07/31/15	
Α			new document. 7/31 - New version to have less screenshots.					
В	2	QR Tag location	Where to place the tags?	Jay	07/27/15			
			Hardware					
	1	Dummy mounting plate rejected	Threads were wrong for collar, date code not stamped in. Waiting for resubmission from supplier.	Stephanie	06/23/15			
	2	L/L, K/K Baldwin spindle	Out for quote. ETA is 7/10/15.	Stephanie	06/23/15	07/10/15		
		L/L, K/K Baldwin BOM	Creating part numbers and entering into JDE	Stephanie	06/23/15			
		Bridge not yet available	Still working through some issues. Should be ready for testing mid	Ashok	06/27/15		07/17/15	
		5	July. 3 GDO units sent on 7/16.					
	5	Battery cover a tight fit, snags on wiring.	Mike to take a look. Possibly change main harness length and add	Doug	06/27/15		07/31/15	
			sleeving, so harness can be routed behind battery housing. ECO-					
	7	New battery housing, 72517	1139. Verify parts when available. 7/27 - order parts Verify in displays. Order several samples	Doug	07/27/15			
		New CPU, 57840 (COMM ASY DOOR) Rev D	Order boards, build samples	Ashok	07/31/15			
Α		Lab testing	Do we send rev C CPUs or wait for Rev D? Need to get tiing from	Doug	07/31/15			
^			Intertek.					
	6	Lithium battery issues (wakeup, cost, availability, etc.)	Decision was made to phase out Lithium battery option, remove harness from CPU. ECO-1138.	Mike	06/27/15			07/17/15
			Training from 61 61 200 1100.					
			Application SW					
Α	1	A new admin can "steal" the lock from a previous	Should the software not allow this to happen? Maybe the CPU	Ashok	06/22/15		06/27/15	
		admin	firmware can lock this out until a factory reset is performed 6/22/15	71011010	00/22/10		00/21/10	
			- This is how it is designed. We need to discuss with Arek if need					
			to change this. 6/27 - May implement a warning screen.					
Α	2	Invite User doesn't send email notifications to new	The fix is in the code, but the UDI Services needs to be updated.	Arek	06/05/15		06/27/15	
		user.						
	1		CPU Firmware					
	-							
			Web Portal					
	2	Cannot schedule users	Access Control Rules in development. 7/17- Web portal functions, but there's a bug in the AM/PM time settings.	Arek	06/05/15	07/31/15	06/27/15	
	3	Cannot operate lock online	In development	Arek	06/24/15		06/27/15	
	4	Cannot check lock status online	In development	Arek	06/24/15		06/27/15	
	5	Push Notifications	Rules for notifications needs to be defined	Arek	06/27/15			
	6	Page layout / appearance	Needs to be reviewed. Doug to set up meeting with Jay and Craig.	Jay	06/27/15	08/07/15		
Α	1	When logging into portal, password is forgotten on	Ashok sent email to Arek on 6/5/15. 6/27 - The fix is in the code,	Arek	06/05/15		06/27/15	07/17/15
		the App.	testing to be complete in 2-3 weeks. 7/17 - tested new code,	AIGK	00/03/13		00/21/13	07/17/13
			appears to be working fine.					