ANSWERS TO SELECTED PROBLEMS

Chapter 2

2.1
$$\mathbf{C} = \begin{bmatrix} 8 & 17 & -3 \\ -1 & -1 & -1 \\ 1 & -7 & 1 \end{bmatrix}; \quad \mathbf{D} = \begin{bmatrix} -2 & -1 & 1 \\ 17 & -13 & -7 \\ -3 & -1 & 9 \end{bmatrix}$$
 2.23 $x_1 = 8.7; x_2 = -7.5; x_3 = -4.2$ **2.25** $x_1 = 6; x_2 = 7; x_3 = 5; x_4 = 2$

2.3
$$\mathbf{C} = -4; \quad \mathbf{D} = \begin{bmatrix} 12 & -18 & 6 \\ 4 & -6 & 2 \\ -2 & 30 & -10 \end{bmatrix}$$

2.5
$$\mathbf{C} = \begin{bmatrix} -18 & -24 & 21 \\ 7 & -9 & 53 \\ 38 & 38 & 58 \end{bmatrix}; \quad \mathbf{D} = \begin{bmatrix} -18 & 7 & 38 \\ -24 & -9 & 38 \\ 21 & 53 & 58 \end{bmatrix}$$

2.9
$$(\mathbf{ABC})^T = \mathbf{C}^T \mathbf{B}^T \mathbf{A}^T$$

$$= \begin{bmatrix} 1,512 & -464 & -1,602 & 1,418 \\ -900 & 5,300 & 200 & -2,100 \\ -810 & -310 & 942 & -620 \\ 270 & 410 & -360 & 130 \end{bmatrix}$$

$$\mathbf{C} = \begin{bmatrix} 332 & 76 & -332 & -76 \\ 76 & 168 & -76 & -168 \\ -332 & -76 & 332 & 76 \\ -76 & -168 & 76 & 168 \end{bmatrix}$$

2.13
$$\frac{d\mathbf{A}}{dx} = \begin{bmatrix} -4x & 3\cos x & -7\\ 3\cos x & -2\sin x\cos x & -9x^2\\ -7 & -9x^2 & 6\sin x\cos x \end{bmatrix}$$

$$\frac{d\mathbf{AB}}{dx} = \begin{bmatrix} -120x^3 & -20x - 60x^2 \\ -90x^2 & -2 - 8x + 45x^4 \\ -6 + 28x + 125x^4 & 28 + 24x^2 \end{bmatrix}$$

2.17
$$\int_{0}^{L} \mathbf{A} dx = \begin{bmatrix} -5L & -L^{3} \\ 2L^{2} & -\frac{L^{4}}{4} \\ \frac{2L^{5}}{5} & 6L \\ \frac{5L^{3}}{3} & -\frac{L^{2}}{2} \end{bmatrix}$$

2.19
$$\int_0^L \mathbf{AB} \, dx$$

$$= \begin{bmatrix} \frac{10L^3}{3} + \frac{9L^4}{4} + \frac{2L^5}{5} & -9L - L^4 - \frac{L^6}{6} \\ -3L^3 + \frac{6L^7}{7} & -\frac{L^4}{2} \end{bmatrix}$$


2.21
$$x_1 = -2$$
; $x_2 = 3$; $x_3 = -5$

2.23
$$x_1 = 8.7$$
; $x_2 = -7.5$; $x_3 = -4.2$

2.25
$$x_1 = 6$$
; $x_2 = 7$; $x_3 = 5$; $x_4 = 2$


2.27
$$\mathbf{A}^{-1} = \begin{bmatrix} 0.44444 & -0.11111 & 0.22222 \\ -0.11111 & 0.16239 & -0.017094 \\ 0.22222 & -0.017094 & 0.26496 \end{bmatrix}$$

$$\mathbf{A}^{-1} = \begin{bmatrix} -0.62656 & -0.71396 & 0.2849 & -0.12372 \\ -0.71396 & -0.6958 & 0.2395 & -0.052213 \\ 0.2849 & 0.2395 & -0.098751 & 0.13053 \\ -0.12372 & -0.052213 & 0.13053 & -0.08059 \end{bmatrix}$$



$$NDOF = 2, NR = 4$$

$$\mathbf{P} = \begin{bmatrix} 12 \\ -20 \end{bmatrix} \mathbf{k}$$



$$\mathbf{P} = \begin{bmatrix} 0 \\ -30 \\ 0 \\ 0 \\ 10 \\ 0 \\ -30 \end{bmatrix} \mathbf{k}$$

3.5
$$\mathbf{k}_1 = \mathbf{k}_3 = \begin{bmatrix} 483.33 & 0 & -483.33 & 0 \\ 0 & 0 & 0 & 0 \\ -483.33 & 0 & 483.33 & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix} \text{k/in}.$$

$$\mathbf{k}_2 = \begin{bmatrix} 402.78 & 0 & -402.78 & 0 \\ 0 & 0 & 0 & 0 \\ -402.78 & 0 & 402.78 & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix} \text{k/in}.$$

3.7 1,540 kN (T)

3.9
$$\mathbf{T}_1 = \begin{bmatrix} 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$\mathbf{T}_{2} = \begin{bmatrix} 0.6 & 0.8 & 0 & 0 \\ -0.8 & 0.6 & 0 & 0 \\ 0 & 0 & 0.6 & 0.8 \\ 0 & 0 & -0.8 & 0.6 \end{bmatrix}$$

$$\mathbf{T}_{3} = \begin{bmatrix} -0.28 & 0.96 & 0 & 0 \\ -0.96 & -0.28 & 0 & 0 \\ 0 & 0 & -0.28 & 0.96 \\ 0 & 0 & 0.28 & 0.96 \end{bmatrix}$$

3.11 and 3.13
$$\mathbf{F}_9 = \begin{bmatrix} -560 \\ -420 \\ 560 \\ 420 \end{bmatrix} \text{kN}; \quad \text{Yes}$$

3.15
$$\mathbf{S} = \begin{bmatrix} 666.23 & 63.413 \\ 63.413 & 703.22 \end{bmatrix}$$
 k/in.

3.17
$$\mathbf{d} = \begin{bmatrix} 0.067082 \\ -0.027951 \end{bmatrix}$$
 in.

$$Q_{a1} = 2.2361 \text{ k (T)}; Q_{a2} = 24.597 \text{ k (C)}$$

$$\mathbf{R} = \begin{bmatrix} -1 \\ -2 \\ -11 \\ 22 \end{bmatrix} \mathbf{k}$$

3.19
$$\mathbf{d} = \begin{bmatrix} -0.06546 \\ -0.10075 \end{bmatrix}$$
 in.

$$Q_{a1} = 31.639 \,\mathrm{k}$$
 (C); $Q_{a2} = 48.283 \,\mathrm{k}$ (C);

$$Q_{a3} = 37.889 \text{ k} (\text{C})$$

$$\mathbf{R} = \begin{bmatrix} 28.97 \\ 38.627 \\ -10.609 \\ 36.373 \\ 31.639 \\ 0 \end{bmatrix} \mathbf{k}$$

$$\mathbf{d} = \begin{bmatrix} 0.2751 \\ -0.32051 \\ 0.23438 \end{bmatrix} \text{ in }$$

$$Q_{a1} = 85.969 \text{ k (T)}; Q_{a2} = 133.55 \text{ k (C)};$$

$$Q_{a3} = 46.875 \text{ k (T)}; Q_{a4} = 19.775 \text{ k (C)};$$

$$Q_{a5} = 46.875 \text{ k} (T)$$

$$\mathbf{R} = \begin{bmatrix} -123.47 \\ 28.125 \\ -26.531 \\ -11.671 \\ 133.55 \end{bmatrix} \mathbf{k}$$

3.23
$$\mathbf{d} = \begin{bmatrix} 1.5685 \\ 0.78427 \\ -1.261 \\ 5.2564 \\ -1.5981 \end{bmatrix} \text{mm}$$

$$Q_{a1} = 78.427 \text{ kN (T)}; \ Q_{a2} = Q_{a3} = 23.836 \text{ kN (C)};$$

$$Q_{a4} = 41.205 \text{ kN (T)}; \ Q_{a5} = 33.709 \text{ kN (C)};$$

$$Q_{a6} = 137.68 \text{ kN (C)}$$

$$\mathbf{R} = \begin{bmatrix} -80 \\ -20 \\ 140 \end{bmatrix} \text{kN}$$

$$\mathbf{d} = \begin{bmatrix} 0.019447 \\ -0.096374 \\ 0.038894 \\ 0.044168 \\ 0.031186 \\ -0.054995 \\ 0.025912 \\ -0.032004 \end{bmatrix} \text{ in.}$$

$$Q_{a1} = Q_{a2} = 18.799 \text{ k} (T); \ Q_{a3} = 5.098 \text{ k} (T);$$

$$Q_{a4} = 5.098 \text{ k (C)}; \ Q_{a5} = 30 \text{ k (T)};$$

$$Q_{a6} = 23.203 \text{ k (C)};$$


$$Q_{a7} = 14.665 \text{ k (C)}; \ Q_{a8} = 22.835 \text{ k (C)};$$

$$Q_{a9} = 8.4966 \text{ k} (\text{C})$$


$$\mathbf{R} = \begin{bmatrix} -10 \\ 11.732 \\ 41.471 \\ 6.7973 \end{bmatrix} \mathbf{k}$$

3.29
$$P = 1,095 \text{ kN}$$

Chapter 5



$$\mathbf{P} = \begin{bmatrix} -25 \,\mathrm{k} \\ 720 \,\mathrm{k\text{-in.}} \end{bmatrix}$$



$$\mathbf{P} = \begin{bmatrix} -150 \\ 0 \end{bmatrix} kN \cdot m$$

5.5 Units: kips and inches

$$\mathbf{k}_1 = \begin{bmatrix} 5.5556 & 500 & -5.5556 & 500 \\ 500 & 60,000 & -500 & 30,000 \\ -5.5556 & -500 & 5.5556 & -500 \\ 500 & 30,000 & -500 & 60,000 \end{bmatrix}$$

$$\mathbf{k}_2 = \begin{bmatrix} 11.111 & 1,000 & -11.111 & 1,000 \\ 1,000 & 120,000 & -1,000 & 60,000 \\ -11.111 & -1,000 & 11.111 & -1,000 \\ 1,000 & 60,000 & -1,000 & 120,000 \end{bmatrix}$$

5.7 Units: kips and inches

$$\begin{aligned} \mathbf{k}_1 &= \mathbf{k}_4 = \begin{bmatrix} 9.4401 & 1,132.8 & -9.4401 & 1,132.8 \\ 1,132.8 & 181,250 & -1,132.8 & 90,625 \\ -9.4401 & -1,132.8 & 9.4401 & -1,132.8 \\ 1,132.8 & 90,625 & -1,132.8 & 181,250 \end{bmatrix} \\ \mathbf{k}_2 &= \mathbf{k}_3 = \begin{bmatrix} 17.901 & 1,611.1 & -17.901 & 1,611.1 \\ 1,611.1 & 193,333 & -1,611.1 & 96,667 \\ -17.901 & -1,611.1 & 17.901 & -1,611.1 \\ 1,611.1 & 96,667 & -1,611.1 & 193,333 \end{bmatrix}$$

$$\mathbf{k}_2 = \mathbf{k}_3 = \begin{bmatrix} 17.901 & 1,611.1 & -17.901 & 1,611.1 \\ 1,611.1 & 193,333 & -1,611.1 & 96,667 \\ -17.901 & -1,611.1 & 17.901 & -1,611.1 \\ 1,611.1 & 96,667 & -1,611.1 & 193,333 \end{bmatrix}$$

5.9
$$\mathbf{Q}_1 = \begin{bmatrix} 2.7848 \text{ k} \\ 1,002.5 \text{ k-in.} \\ -2.7848 \text{ k} \\ -501.23 \text{ k-in.} \end{bmatrix}; \text{ Yes}$$

5.11
$$FS_b = FS_e = \frac{wL}{2}$$
; $FM_b = -FM_e = \frac{wL^2}{12}$

5.13
$$FS_b = \frac{7wL}{20}$$
; $FM_b = \frac{wL^2}{20}$; $FS_e = \frac{3wL}{20}$; $FM_e = -\frac{wL^2}{30}$

5.15
$$\mathbf{Q}_{f1} = \begin{bmatrix} 135 \text{ kN} \\ 337.5 \text{ kN} \cdot \text{m} \\ 135 \text{ kN} \\ -337.5 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{f2} = \begin{bmatrix} 90 \text{ kN} \\ 300 \text{ kN} \cdot \text{m} \\ 90 \text{ kN} \\ -300 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_{f3} = \begin{bmatrix} 131.25 \text{ kN} \\ 281.25 \text{ kN} \cdot \text{m} \\ 56.25 \text{ kN} \\ -187.5 \text{ kN} \cdot \text{m} \end{bmatrix}$$

5.17
$$\mathbf{Q}_1 = \begin{bmatrix} 69.52 \text{ k} \\ 4,945.9 \text{ k-in.} \\ 2.48 \text{ k} \\ 4,707.8 \text{ k-in.} \end{bmatrix}; \text{ Yes}$$

5.19 Units: kips and inches

$$\mathbf{S} = \begin{bmatrix} 16.667 & 500 \\ 500 & 180,000 \end{bmatrix}$$

5.21 Units: kips and inches

$$\mathbf{S} = \begin{bmatrix} 27.341 & 478.3 & 1,611.1 & 0 & 0\\ 478.3 & 374,583 & 96,667 & 0 & 0\\ 1,611.1 & 96,667 & 386,667 & -1,611.1 & 96,667\\ 0 & 0 & -1,611.1 & 27.341 & -478.3\\ 0 & 0 & 96,667 & -478.3 & 374,583 \end{bmatrix}$$

5.23 Units: kips and inches

$$\mathbf{P}_f = -\mathbf{P}_e = \begin{bmatrix} 0\\30\\360 \end{bmatrix}$$

5.25 Units: kN and meters

$$\mathbf{P}_f = -\mathbf{P}_e = \begin{bmatrix} 337.5 \\ -37.5 \\ -18.75 \\ -187.5 \end{bmatrix}$$

5.27
$$\mathbf{d} = \begin{bmatrix} -1.7673 \text{ in.} \\ 0.0089091 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 14.273 \text{ k} \\ 1,150.9 \text{ k-in.} \\ -14.273 \text{ k} \\ 1,418.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} \\ \\ - \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 14.273 \text{ k} \\ 1,150.9 \text{ k-in.} \\ 10.727 \text{ k} \\ -1,232.7 \text{ k-in.} \end{bmatrix}$$

5.29
$$\mathbf{d} = \begin{bmatrix} -0.007619 \\ 0.0019048 \end{bmatrix} \text{rad}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} -20 \text{ kN} \\ -40 \text{ kN} \cdot \text{m} \\ 20 \text{ kN} \\ -80 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} -15 \text{ kN} \\ -70 \text{ kN} \cdot \text{m} \\ 15 \text{ kN} \\ -20 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 5 \text{ kN} \\ 20 \text{ kN} \cdot \text{m} \\ -5 \text{ kN} \\ 10 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{R} = \begin{bmatrix} -20 \text{ kN} \\ -40 \text{ kN} \cdot \text{m} \\ 5 \text{ kN} \\ 20 \text{ kN} \\ -5 \text{ kN} \\ 10 \text{ kN} \cdot \text{m} \end{bmatrix}$$

5.31
$$\mathbf{d} = \begin{bmatrix} 0.014375 \\ -0.011422 \\ 0.014244 \end{bmatrix} \text{ rad}$$

$$\mathbf{Q}_1 = \begin{bmatrix} 41.615 \text{ k} \\ 2,267.1 \text{ k-in.} \\ 30.385 \text{ k} \\ -649.85 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_2 = \begin{bmatrix} 1.1538 \text{ k} \\ 649.85 \text{ k-in.} \\ -1.1538 \text{ k} \\ -317.54 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 11.103 \text{ k} \\ 317.54 \text{ k-in.} \\ 8.8974 \text{ k} \\ 0 \end{bmatrix} \qquad \mathbf{R} = \begin{bmatrix} 41.615 \text{ k} \\ 2,267.1 \text{ k-in.} \\ 31.538 \text{ k} \\ 9.9487 \text{ k} \\ 8.8974 \text{ k} \end{bmatrix}$$

$$\mathbf{d} = \begin{bmatrix} -0.019391 \\ 0.0071406 \\ -0.0056563 \\ 0.017242 \end{bmatrix} \text{ rad}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 108.87 \text{ kN} \\ 0 \\ 161.13 \text{ kN} \\ -392 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 93.167 \text{ kN} \\ 392 \text{ kN} \cdot \text{m} \\ 86.833 \text{ kN} \\ -344.5 \text{ kN} \cdot \text{m} \end{bmatrix}$$


$$\mathbf{Q}_{1} = \begin{bmatrix} 14.273 \text{ k} \\ 1,150.9 \text{ k-in.} \\ -14.273 \text{ k} \\ 1,418.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} -10.727 \text{ k} \\ -698.18 \text{ k-in.} \\ 10.727 \text{ k} \\ -1,232.7 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{3} = \begin{bmatrix} 155.97 \text{ kN} \\ 344.5 \text{ kN} \cdot \text{m} \\ 31.533 \text{ kN} \\ 120 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{R} = \begin{bmatrix} 108.87 \\ 254.3 \\ 242.8 \\ 31.533 \end{bmatrix} \text{kN}$$

5.35

$$\mathbf{d} = \begin{bmatrix}
-1.8705 \text{ in.} \\
0.0023884 \text{ rad} \\
0 \\
-1.8705 \text{ in.} \\
-0.0023884 \text{ rad}
\end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 29.637 \text{ k} \\ 2,782.7 \text{ k-in.} \\ -29.637 \text{ k} \\ 2,551.8 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{4} = \begin{bmatrix} -20.363 \text{ k} \\ -2,551.8 \text{ k-in.} \\ 20.363 \text{ k} \\ -2,335.4 \text{ k-in.} \end{bmatrix}$$


$$\mathbf{R} = \begin{bmatrix} 20.363 \text{ k} \\ 2,335.4 \text{ k-in.} \\ 59.273 \text{ k} \\ 20.363 \text{ k} \\ -2,335.4 \text{ k-in.} \end{bmatrix}$$




$$NDOF = 2, NR =$$

$$P = 0$$

6.5



$$\mathbf{P} = \begin{bmatrix} 0 \\ 0 \\ -900 \text{ k-in.} \end{bmatrix}$$



6.7 Units: kips and inches

$$\mathbf{k}_1 = \begin{bmatrix} 1,244.6 & 0 & 0 & -1,244.6 & 0 & 0 & -1,00 \\ 0 & 12.839 & 1,540.6 & 0 & -12.839 & 1,540.6 \\ 0 & 1,540.6 & 246,500 & 0 & -1,540.6 & 123,250 \\ -1,244.6 & 0 & 0 & 1,244.6 & 0 & 0 \\ 0 & -12.839 & -1,540.6 & 0 & 12.839 & -1,540.6 \\ 0 & 1.540.6 & 123.250 & 0 & -1,540.6 & 246,500 \end{bmatrix}$$

$$\mathbf{k}_2 = \begin{bmatrix} 829.72 & 0 & 0 & -829.72 & 0 & 0 \\ 0 & 3.804 & 684.72 & 0 & -3.804 & 684.72 \\ 0 & 684.72 & 164,333 & 0 & -684.72 & 82,167 \\ -829.72 & 0 & 0 & 829.72 & 0 & 0 \\ 0 & -3.804 & -684.72 & 0 & 3.804 & -684.72 \\ 0 & 684.72 & 82,167 & 0 & -684.72 & 164,333 \end{bmatrix} \qquad \mathbf{Q}_{f1} = \begin{bmatrix} 0 \\ 20 \\ 1,200 \\ 0 \\ 20 \\ -1,200 \end{bmatrix} \qquad \mathbf{Q}_{f2} = \begin{bmatrix} 0 \\ 22.5 \\ 1,350 \\ 0 \\ 22.5 \\ -1,350 \end{bmatrix}$$

$$\mathbf{Q}_{f1} = \begin{bmatrix} 0 \\ 20 \\ 1,200 \\ 0 \\ 20 \\ -1,200 \end{bmatrix} \quad \mathbf{Q}_{f2} = \begin{bmatrix} 0 \\ 22.5 \\ 1,350 \\ 0 \\ 22.5 \\ -1,350 \end{bmatrix}$$

6.9 Units: kips and inches

$$\mathbf{k}_1 = \begin{bmatrix} 409.26 & 0 & 0 & -409.26 & 0 & 0 \\ 0 & 2.0243 & 218.62 & 0 & -2.0243 & 218.62 \\ 0 & 218.62 & 31.481 & 0 & -218.62 & 15.741 \\ -409.26 & 0 & 0 & 409.26 & 0 & 0 \\ 0 & -2.0243 & -218.62 & 0 & 2.0243 & -218.62 \\ 0 & 218.62 & 15.741 & 0 & -218.62 & 31.481 \end{bmatrix}$$

$$\mathbf{k}_{2} = \begin{bmatrix} 491.11 & 0 & 0 & -491.11 & 0 & 0 \\ 0 & 3.4979 & 314.81 & 0 & -3.4979 & 314.81 \\ 0 & 314.81 & 37,778 & 0 & -314.81 & 18,889 \\ -491.11 & 0 & 0 & 491.11 & 0 & 0 \\ 0 & -3.4979 & -314.81 & 0 & 3.4979 & -314.81 \\ 0 & 314.81 & 18,889 & 0 & -314.81 & 37,778 \end{bmatrix} \quad \mathbf{Q}_{f1} = \begin{bmatrix} 0 \\ 27 \\ 972 \\ 0 \\ 27 \\ -972 \end{bmatrix} \quad \mathbf{Q}_{f2} = \begin{bmatrix} -4.5 \\ 6 \\ 270 \\ -4.5 \\ 6 \\ -270 \end{bmatrix}$$

$$\mathbf{Q}_{f1} = \begin{bmatrix} 0 \\ 27 \\ 972 \\ 0 \\ 27 \\ -972 \end{bmatrix} \qquad \mathbf{Q}_{f2} = \begin{bmatrix} -4.5 \\ 6 \\ 270 \\ -4.5 \\ 6 \\ -270 \end{bmatrix}$$

6.11 Units: kips and inches

$$\mathbf{k}_1 = \mathbf{k}_3 = \begin{bmatrix} 1,500 & 0 & 0 & -1,500 & 0 & 0 \\ 0 & 2.1484 & 257.81 & 0 & -2.1484 & 257.81 \\ 0 & 257.81 & 41,250 & 0 & -257.81 & 20,625 \\ -1,500 & 0 & 0 & 1,500 & 0 & 0 \\ 0 & -2.1484 & -257.81 & 0 & 2.1484 & -257.81 \\ 0 & 257.81 & 20,625 & 0 & -257.81 & 41,250 \end{bmatrix}$$

$$\mathbf{k}_2 = \begin{bmatrix} 1,620 & 0 & 0 & -1,620 & 0 & 0 \\ 0 & 2.6 & 390 & 0 & -2.6 & 390 \\ 0 & 390 & 78,000 & 0 & -390 & 39,000 \\ -1,620 & 0 & 0 & 1,620 & 0 & 0 \\ 0 & -2.6 & -390 & 0 & 2.6 & -390 \\ 0 & 390 & 39,000 & 0 & -390 & 78,000 \end{bmatrix} \quad \mathbf{Q}_{f1} = \mathbf{Q}_{f3} = \mathbf{0}; \qquad \mathbf{Q}_{f2} = \begin{bmatrix} 0 \\ 25 \\ 1,250 \\ 0 \\ 25 \\ -1,250 \end{bmatrix}$$

6.13
$$FA_b = \frac{Wl_2}{L}$$
; $FA_e = \frac{Wl_1}{L}$; $FS_b = FS_e = FM_b = FM_e = 0$

$$\mathbf{Q}_{1} = \begin{bmatrix} 128.12 \text{ k} \\ -78.786 \text{ k} \\ -5,875 \text{ k-in.} \\ -128.12 \text{ k} \\ 98.786 \text{ k} \\ -5,179.3 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 111.62 \text{ k} \\ 11.038 \text{ k} \\ 1,942.5 \text{ k-in.} \\ -140.46 \text{ k} \\ -80.268 \text{ k} \\ 5,179.3 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{3} = \begin{bmatrix} -70.97 \text{ k} \\ -20.192 \text{ k} \\ -2,176.6 \text{ k-in.} \\ 70.97 \text{ k} \\ 20.192 \text{ k} \\ -1,942.5 \text{ k-in.} \end{bmatrix}; \text{ Yes}$$

$$\mathbf{T}_1 = \begin{bmatrix} -0.6 & 0.8 & 0 & 0 & 0 & 0 \\ -0.8 & -0.6 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & -0.6 & 0.8 & 0 \\ 0 & 0 & 0 & -0.8 & -0.6 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix}; \; \mathbf{T}_2 = \mathbf{I}$$

$$\mathbf{T}_1 = \begin{bmatrix} 0 & 1 & 0 & 0 & 0 & 0 \\ -1 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & -1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix} \qquad \mathbf{T}_2 = \begin{bmatrix} -0.96 & 0.28 & 0 & 0 & 0 & 0 \\ -0.28 & -0.96 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & -0.96 & 0.28 & 0 \\ 0 & 0 & 0 & -0.28 & -0.96 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix}$$

$$\mathbf{T}_1 = \begin{bmatrix} 0.44721 & 0.89443 & 0 & 0 & 0 & 0 \\ -0.89443 & 0.44721 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0.44721 & 0.89443 & 0 \\ 0 & 0 & 0 & -0.89443 & 0.44721 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix} \qquad \mathbf{T}_2 = \mathbf{I}$$

6.23 and 6.31

$$\mathbf{v}_1 = \begin{bmatrix} 0 \\ 0 \\ 0 \\ -2.0939 \text{ in.} \\ -0.05147 \text{ in.} \\ 0.0079542 \text{ rad} \end{bmatrix} \qquad \mathbf{v}_2 = \begin{bmatrix} -1.8078 \text{ in.} \\ -0.90922 \text{ in.} \\ 0.0028882 \text{ rad} \\ -2.0939 \text{ in.} \\ -0.05147 \text{ in.} \\ 0.0079542 \text{ rad} \end{bmatrix} \qquad \mathbf{v}_3 = \begin{bmatrix} 0 \\ 0 \\ 0 \\ -1.8078 \text{ in.} \\ -0.90922 \text{ in.} \\ 0.0028882 \text{ rad} \end{bmatrix}$$

$$\mathbf{F}_{1} = \begin{bmatrix} 78.786 \text{ k} \\ 128.12 \text{ k} \\ -5,875 \text{ k-in.} \\ -98.786 \text{ k} \\ -128.12 \text{ k} \\ -5,179.3 \text{ k-in.} \end{bmatrix} \qquad \mathbf{F}_{2} = \begin{bmatrix} -98.786 \text{ k} \\ -53.119 \text{ k} \\ 1,942.5 \text{ k-in.} \\ 98.786 \text{ k} \\ 128.12 \text{ k} \\ 5,179.3 \text{ k-in.} \end{bmatrix} \qquad \mathbf{F}_{3} = \begin{bmatrix} 51.214 \text{ k} \\ -53.119 \text{ k} \\ -2,176.6 \text{ k-in.} \\ -51.214 \text{ k} \\ 53.119 \text{ k} \\ -1,942.5 \text{ k-in.} \end{bmatrix}; \text{ Yes}$$

6.25 Units: kN and meters

$$\mathbf{K}_1 = \begin{bmatrix} 94,770 & -123,922 & -7,315.2 & -94,770 & 123,922 & -7,315.2 \\ 167,058 & -5,486.4 & 123,922 & -167,058 & -5,486.4 \\ & 60,960 & 7,315.2 & 5,486.4 & 30,480 \\ (symmetric) & 94,770 & -123,922 & 7,315.2 \\ & & 167,058 & 5,486.4 \\ & & 60,960 \end{bmatrix}$$

$$\mathbf{F}_{f1} = \begin{bmatrix} 50\\ 37.5\\ -156.25\\ 50\\ 37.5\\ 156.25 \end{bmatrix} \quad \mathbf{F}_{f2} = \begin{bmatrix} 0\\ 144\\ 288\\ 0\\ 144\\ -288 \end{bmatrix}$$

6.27 Units: kN and meters

$$\mathbf{K}_{1} = \begin{bmatrix} 694.92 & 0 & -5,559.4 & -694.92 & 0 & -5,559.4 \\ 200,000 & 0 & 0 & -200,000 & 0 \\ 59,300 & 5,559.4 & 0 & 29,650 \\ 694.92 & 0 & 5,559.4 \\ 200,000 & 0 \\ 59,300 \end{bmatrix}$$

$$\mathbf{K}_2 = \begin{bmatrix} 117,980 & -34,357 & -637.59 & -117,980 & 34,357 & -637.59 \\ 10,203 & -2,186 & 34,357 & -10,203 & -2,186 \\ & & 37,952 & 637.59 & 2,186 & 18,976 \\ & & & 117,980 & -34,357 & 637.59 \\ & & & & 10,203 & 2,186 \\ & & & & 37,952 \end{bmatrix}$$

$$\mathbf{F}_{f1} = \mathbf{0}; \qquad \mathbf{F}_{f2} = \begin{bmatrix} 0 \\ 250 \\ -1,000 \\ 0 \\ 250 \\ 1,000 \end{bmatrix}$$

6.29 Units: kips and inches

$$\mathbf{F}_{f1} = \begin{bmatrix} 0\\11.18\\223.61\\0\\11.18\\-223.61 \end{bmatrix} \quad \mathbf{F}_{f2} = \begin{bmatrix} 0\\16.25\\875\\0\\21.25\\-1,000 \end{bmatrix}$$

6.33 Units: kN and meters

$$\mathbf{S} = \begin{bmatrix} 311,437 & -7,315.2 & 0 \\ -7,315.2 & 111,760 & 25,400 \\ 0 & 25,400 & 50,800 \end{bmatrix} \qquad \mathbf{P}_f = -\mathbf{P}_e = \begin{bmatrix} 50 \\ 131.75 \\ -288 \end{bmatrix}$$

6.35 Units: kN and meters

$$\mathbf{S} = \begin{bmatrix} 210,203 & -2,186 \\ -2,186 & 97,252 \end{bmatrix} \qquad \mathbf{P}_f = -\mathbf{P}_e = \begin{bmatrix} 250 \\ -1,000 \end{bmatrix}$$

6.37 Units: kips and inches

$$\mathbf{S} = \begin{bmatrix} 382.19 & 152.84 & 212.43 & 0 \\ 152.84 & 309.11 & 143.79 & 250 \\ 212.43 & 143.79 & 92,485 & 25,000 \\ 0 & 250 & 25,000 & 50,000 \end{bmatrix} \qquad \mathbf{P}_f = -\mathbf{P}_e = \begin{bmatrix} 0 \\ 27.431 \\ 651.4 \\ -1,000 \end{bmatrix}$$

6.39

$$\mathbf{P} = \begin{bmatrix} 0 \\ 0 \\ -30 \text{ k} \\ -180 \text{ k-in.} \\ 45 \text{ k} \\ 0 \\ 240 \text{ k-in.} \end{bmatrix}$$

$$\begin{array}{c} \textbf{6.41} \ \mathbf{d} = \begin{bmatrix} 0.0034433 \ \text{in.} \\ 0.0029828 \ \text{rad} \\ 0.0039828 \ \text{rad} \\ 0.16132 \ k \\ 517.88 \ k \cdot \text{in.} \\ 7.3457 \ k \\ 13.869 \ k \\ -3.14.26 \ k \cdot \text{in.} \\ 13.182 \ k \cdot \text{in.} \\ 13.182 \ k \cdot \text{in.} \\ 13.182 \ k \cdot \text{in.} \\ -7.3457 \ k \\ 13.182 \ k \cdot \text{in.} \\ -3.14.26 \ k \cdot \text{in.} \\ -1.7167 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_2 = \begin{bmatrix} 3.2599 \ k \\ -3.2599 \ k \\ 0.43406 \ k \\ -1.7167 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_1 = \begin{bmatrix} 4.5.788 \ k \\ -1.751 \ k \\ -813.28 \ k \cdot \text{in.} \\ -25.787 \ k \\ -813.28 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_2 = \begin{bmatrix} 18.907 \ k \\ 19.378 \ k \\ 813.28 \ k \cdot \text{in.} \\ -1.7167 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_1 = \begin{bmatrix} 4.5.788 \ k \\ -1.751 \ k \cdot \text{in.} \\ -25.787 \ k \\ -813.28 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_2 = \begin{bmatrix} 18.907 \ k \\ 41.739 \ k \\ -1.7167 \ k \cdot \text{in.} \end{bmatrix} \\ \textbf{Q}_2 = \begin{bmatrix} -5.6.756 \ kN \\ 16.629 \ kN \\ 26.751 \ kN \cdot m \\ -40.864 \ kN \\ -23.3406 \ kN \\ -23.406 \ kN \\ -23.406 \ kN \\ -23.406 \ kN \\ -25.778 \ kN \cdot m \\ 25.994 \ kN \\ 5.6756 \ kN \\ 121.71 \ kN \end{bmatrix} \\ \textbf{Q}_1 = \begin{bmatrix} 43.244 \ kN \\ -18.648 \ kN \\ 26.577 \ kN \cdot m \\ 25.994 \ kN \\ 5.7029 \ kN \\ -216.53 \ kN \\ -57.029 \ kN \\ 608.31 \ kN \cdot m \\ -608.31 \ kN \cdot m \\ 608.31 \ kN \cdot m \\ -26.555 \ kN \\ -216.53 \ kN \\ -57.029 \ kN \\ 216.53 \ kN \\ -30.0416 \ kN \cdot m \\ 87.686 \ kN \\ -26.555 \ kN \\ -20.656 \ k$$

 $1,197 \text{ kN} \cdot \text{m}$

$$\mathbf{R} = \begin{bmatrix} 24.591 \text{ k} \\ 2,301.9 \text{ k-in.} \\ 0 \\ 27.909 \text{ k} \\ -2,998.6 \text{ k-in.} \end{bmatrix}$$

7.3
$$\mathbf{d} = \begin{bmatrix} 0.014375 \\ -0.011422 \end{bmatrix} \text{ rad}$$

$$\mathbf{d} = \begin{bmatrix} 0.014375 \\ -0.011422 \end{bmatrix} \text{ rad}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 41.615 \text{ k} \\ 2,267.1 \text{ k-in.} \\ 30.385 \text{ k} \\ -649.85 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 1.1538 \text{ k} \\ 649.85 \text{ k-in.} \\ -1.1538 \text{ k} \\ -317.54 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 11.103 \text{ k} \\ 317.54 \text{ k-in.} \\ 8.8974 \text{ k} \end{bmatrix} \quad \mathbf{R} = \begin{bmatrix} 41.615 \text{ k} \\ 2,267.1 \text{ k-in.} \\ 31.538 \text{ k} \\ 9.9487 \text{ k} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 94.605 \text{ kN} \\ 46.434 \text{ kN} \\ 0 \\ -94.605 \text{ kN} \\ 73.566 \text{ kN} \\ -135.66 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 175.62 \text{ kN} \\ -13.456 \text{ kN} \\ 0 \\ -115.62 \text{ kN} \\ -31.544 \text{ kN} \\ 135.66 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 11.103 \text{ k} \\ 317.54 \text{ k-in.} \\ 8.8974 \text{ k} \\ 0 \end{bmatrix} \quad \mathbf{R} = \begin{bmatrix} 41.615 \text{ k} \\ 2,267.1 \text{ k-in.} \\ 31.538 \text{ k} \\ 9.9487 \text{ k} \\ 8.8974 \text{ k} \\ 0 \end{bmatrix}$$

7.5
$$\mathbf{d} = \begin{bmatrix} 0.0071406 \\ -0.0056563 \\ 0.017242 \end{bmatrix} \text{rad}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 108.87 \text{ kN} \\ 0 \\ 161.13 \text{ kN} \\ -392 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 93.167 \text{ kN} \\ 392 \text{ kN} \cdot \text{m} \\ 86.833 \text{ kN} \\ -344.5 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \begin{array}{c} \textbf{7.13} \ P_{max} = 47.453 \text{ kN} \\ \textbf{7.17} \\ \textbf{d} = \begin{bmatrix} 0.23122 \\ -0.36987 \\ 0.14063 \end{bmatrix} \text{ in.} \\ \end{array}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 155.97 \text{ kN} \\ 344.5 \text{ kN} \cdot \text{m} \\ 31.533 \text{ kN} \\ 120 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{R} = \begin{bmatrix} 108.87 \text{ kN} \\ 0 \\ 254.3 \text{ kN} \\ 242.8 \text{ kN} \\ 31.533 \text{ kN} \end{bmatrix}$$

7.7
$$\mathbf{d} = \begin{bmatrix} -0.00026195 \text{ m} \\ -0.0043172 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 40.864 \text{ kN} \\ -101.59 \text{ kN} \\ -417.51 \text{ kN} \cdot \text{m} \\ -40.864 \text{ kN} \\ -23.406 \text{ kN} \\ 26.577 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} -56.756 \text{ kN} \\ 166.29 \text{ kN} \\ 267.51 \text{ kN} \cdot \text{m} \\ 56.756 \text{ kN} \\ 121.71 \text{ kN} \\ 0 \end{bmatrix} \quad \mathbf{Q}_{1} = \begin{bmatrix} -4.87 \text{ kN} \\ -1.8939 \text{ kN} \cdot \text{m} \\ 4.87 \text{ kN} \\ -32.196 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 15.624 \text{ kN} \\ 32.196 \text{ kN} \cdot \text{m} \\ -15.624 \text{ kN} \\ 77.176 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 43.244 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & 26.577 \text{ kN} \cdot \text{m} \\ 259.94 \text{ kN} & 56.756 \text{ kN} \\ 121.71 \text{ kN} & 0 & -18.648 \text{ kN} \\ 0 & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -18.648 \text{ kN} & -18.648 \text{ kN} \\ -18.648 \text{ kN} & -1$$

7.9
$$\mathbf{d} = \begin{bmatrix} -0.000901 \text{ m} \\ -0.003276 \text{ m} \\ 0.010155 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_1 = \begin{bmatrix} 94.605 \text{ kN} \\ 46.434 \text{ kN} \\ 0 \\ -94.605 \text{ kN} \\ 73.566 \text{ kN} \\ -135.66 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_{2} = \begin{bmatrix} 175.62 \text{ kN} \\ -13.456 \text{ kN} \\ 0 \\ -115.62 \text{ kN} \\ -31.544 \text{ kN} \\ 135.66 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 94.605 \text{ kN} \\ 46.434 \text{ kN} \\ 0 \\ -94.605 \text{ kN} \\ 148.57 \text{ kN} \\ 0 \end{bmatrix}$$

7.11
$$P_{\text{max}} = 951.36 \,\text{kN}$$

7.13
$$P_{\text{max}} = 47.453 \,\text{kN}$$

7.17
$$\mathbf{d} = \begin{bmatrix} 0.23122 \\ -0.36987 \\ 0.14063 \end{bmatrix} \text{ in.}$$

$$Q_{a1} = 72.258 \text{ k (T)}; Q_{a2} = 154.11 \text{ k (C)};$$

$$Q_{a3} = 28.125 \text{ k (T)}; Q_{a4} = 4.9438 \text{ k (T)};$$

$$Q_{a5} = 65.625 \text{ k} (\text{T})$$

$$\mathbf{R} = \begin{bmatrix} -94.758 \\ 16.875 \\ -55.242 \\ -43.489 \\ 176.61 \end{bmatrix} \mathbf{k}$$

7.19
$$\mathbf{d} = \begin{bmatrix} -0.0036571 \\ 0.0017714 \end{bmatrix}$$
 rad

$$\mathbf{Q}_{1} = \begin{bmatrix} -4.87 \text{ kN} \\ -1.8939 \text{ kN} \cdot \text{m} \\ 4.87 \text{ kN} \\ -32.196 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_2 = \begin{bmatrix} 15.624 \text{ kN} \\ 32.196 \text{ kN} \cdot \text{m} \\ -15.624 \text{ kN} \\ 77.176 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} -24.147 \text{ kN} \\ -77.176 \text{ kN} \cdot \text{m} \\ 24.147 \text{ kN} \\ -91.853 \text{ kN.m} \end{bmatrix} \qquad \mathbf{R} = \begin{bmatrix} -4.87 \text{ kN} \\ -1.8939 \text{ kN} \cdot \text{m} \\ 20.494 \text{ kN} \\ -39.771 \text{ kN} \\ 24.147 \text{ kN} \\ -91.853 \text{ kN} \cdot \text{m} \end{bmatrix} \qquad \mathbf{Q}_{a1} = 95.262 \text{ k (T)}; \ \mathbf{Q}_{a2} = 35.175 \text{ k (T)}; \ \mathbf{Q}_{a4} = 95.262 \text{ k (T)}; \ \mathbf{Q}_{a5} = 58.575 \text{ k (T)}$$

$$\mathbf{d} = \begin{bmatrix} 0.56464 \\ -0.15602 \\ 0.17587 \end{bmatrix} \text{ in.}$$

$$Q_{a1} = 95.262 \text{ k (T)}; \ Q_{a2} = 119.61 \text{ k (C)};$$

$$Q_{a3} = 35.175 \text{ k (T)}; \ Q_{a4} = 36.527 \text{ k (C)};$$

$$Q_{a5} = 58.575 \text{ k (T)}$$

$$\mathbf{R} = \begin{bmatrix} -123.4 \\ 21.105 \\ -26.598 \\ -4.7525 \\ 122.65 \end{bmatrix} \text{ k}$$

7.21
$$\mathbf{d} = \begin{bmatrix} -2.6114 \text{ in.} \\ -0.0020419 \text{ rad} \\ 0 \\ -22.6114 \text{ in.} \\ 0.0020419 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_1 = \begin{bmatrix} 22.339 \text{ k} \\ 2,773.2 \text{ k-in.} \\ -22.339 \text{ k} \\ 2,588.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_2 = \begin{bmatrix} -27.661 \text{ k} \\ -2,588.2 \text{ k-in.} \\ 27.661 \text{ k} \\ -2,390.8 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 27.661 \text{ k} \\ 2,390.8 \text{ k-in.} \\ -27.661 \text{ k} \\ 2,588.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{4} = \begin{bmatrix} -22.339 \text{ k} \\ -2,588.2 \text{ k-in.} \\ 22.339 \text{ k} \\ -2,773.2 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 22.339 \text{ k} \\ 2,773.2 \text{ k-in.} \\ 55.322 \text{ k} \\ 22.339 \text{ k} \\ -2.773.2 \text{ k-in.} \end{bmatrix}$$

7.23
$$\mathbf{d} = \begin{bmatrix} -0.00089687 \text{ m} \\ -0.053264 \text{ m} \\ 0.0071551 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 94.171 \text{ kN} \\ 46.707 \text{ kN} \\ 0 \\ -94.171 \text{ kN} \\ 73.293 \text{ kN} \\ -132.93 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 94.171 \text{ kN} \\ 46.707 \text{ kN} \\ 0 \\ -94.171 \text{ kN} \\ 148.29 \text{ kN} \\ 0 \end{bmatrix}$$

7.31
$$\mathbf{d} = \begin{bmatrix} 0.0053481 \text{ m} \\ 0.0035829 \text{ m} \\ -0.00056336 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 22.339 \text{ k} \\ 2,773.2 \text{ k-in.} \\ -22.339 \text{ k} \\ 2,588.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} -27.661 \text{ k} \\ -2,588.2 \text{ k-in.} \\ 27.661 \text{ k} \\ -2,390.8 \text{ k-in.} \end{bmatrix} \quad \mathbf{d} = \begin{bmatrix} 0.0053481 \text{ m} \\ 0.0035829 \text{ m} \\ -0.00056336 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{3} = \begin{bmatrix} 27.661 \text{ k} \\ 2,390.8 \text{ k-in.} \\ -27.661 \text{ k} \\ 2,588.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{4} = \begin{bmatrix} -22.339 \text{ k} \\ -2,588.2 \text{ k-in.} \\ -2,588.2 \text{ k-in.} \\ 22.339 \text{ k} \\ -2,773.2 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_{1} = \begin{bmatrix} 8.7792 \text{ kN} \\ -4.3505 \text{ kN} \\ -8.7792 \text{ kN} \\ 4.3505 \text{ kN} \\ -8.7792 \text{ kN} \\ -22.282 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 4.3505 \text{ kN} \\ 8.7792 \text{ kN} \\ 30.394 \text{ kN} \cdot \text{m} \\ -4.3505 \text{ kN} \\ -8.7792 \text{ kN} \\ -22.282 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 8.7792 \text{ kN} \\ -4.3505 \text{ kN} \\ -16.873 \text{ kN} \cdot \text{m} \\ -8.7792 \text{ kN} \\ 4.3505 \text{ kN} \\ 30.394 \text{ kN} \cdot \text{m} \end{bmatrix}$$

7.33
$$\mathbf{d} = \begin{bmatrix} -0.0068989 \text{ m} \\ -0.01902 \text{ m} \\ 0.0095899 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_{1} = \begin{bmatrix} 94.171 \text{ kN} \\ 46.707 \text{ kN} \\ 0 \\ -94.171 \text{ kN} \\ 73.293 \text{ kN} \\ -132.93 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 175.14 \text{ kN} \\ -13.638 \text{ kN} \\ 0 \\ -115.14 \text{ kN} \\ -31.362 \text{ kN} \\ 132.93 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{1} = \begin{bmatrix} 94.386 \text{ kN} \\ 46.572 \text{ kN} \\ 0 \\ -94.386 \text{ kN} \\ 73.428 \text{ kN} \\ -134.28 \text{ kN} \cdot \text{m} \end{bmatrix} \quad \mathbf{Q}_{2} = \begin{bmatrix} 175.37 \text{ kN} \\ -13.548 \text{ kN} \\ 0 \\ -115.37 \text{ kN} \\ -31.452 \text{ kN} \\ 134.28 \text{ kN} \cdot \text{m} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 94.386 \text{ kN} \\ 46.572 \text{ kN} \\ 0 \\ -94.386 \text{ kN} \\ 148.43 \text{ kN} \end{bmatrix}$$

$$\mathbf{Q}_{2} = \begin{bmatrix} 175.37 \text{ kN} \\ -13.548 \text{ kN} \\ 0 \\ -115.37 \text{ kN} \\ -31.452 \text{ kN} \\ 124.28 \text{ kN} \end{bmatrix}$$

$$\mathbf{d} = \begin{bmatrix} 17.871 \\ -5.0794 \\ -7.7663 \end{bmatrix} \text{mm}$$

$$Q_{a1} = 24.768 \text{ kN (T)}; Q_{a2} = 93.974 \text{ kN (C)};$$

$$Q_{a3} = 107 \text{ kN (C)}$$

$$\mathbf{R} = \begin{bmatrix} -5.5693 \\ -22.277 \\ 9.2822 \\ -52.351 \\ 69.802 \\ -34.901 \\ -17.079 \\ 102.48 \\ 25.619 \end{bmatrix} \text{kN}$$

$$\mathbf{d} = \begin{bmatrix} 1.0795 \\ -0.59449 \\ -1.4492 \end{bmatrix} \text{mm}$$

$$Q_{a1} = 12.47 \text{ kN (T)}; Q_{a2} = 15.37 \text{ kN (T)};$$

$$Q_{a3} = 67.569 \text{ kN (C)}; Q_{a4} = 81.813 \text{ kN (C)}$$

$$\mathbf{R} = \begin{bmatrix} -7.7899 \\ -9.7373 \\ 0 \\ 0 \\ -13.179 \\ 7.9076 \\ -42.21 \\ 52.763 \\ 0 \\ 0 \\ 70.154 \\ 42.092 \end{bmatrix} \text{kN}$$

$$\mathbf{d} = \begin{bmatrix} 4.3357 \\ -1.8141 \\ 1.5783 \\ 4.0207 \\ -1.5814 \\ -1.6683 \\ 0.77404 \\ -0.79219 \\ -1.5783 \\ 0.86404 \\ -0.97997 \\ 1.6683 \end{bmatrix} \text{ mm} \quad \mathbf{R} = \begin{bmatrix} -15.75 \\ 33.75 \\ -6.75 \\ 146.25 \\ -29.25 \\ -51.75 \\ 146.25 \\ 29.25 \\ 6.75 \\ 33.75 \\ 6.75 \end{bmatrix} \text{ kN}$$

$$Q_{a1} = Q_{a3} = 93.531 \text{ kN (C)}; Q_{a2} = 151.99 \text{ kN (C)};$$

$$Q_{a4} = 35.074 \text{ kN (C)}; Q_{a5} = 66.556 \text{ kN (T)};$$

$$Q_{a6} = Q_{a8} = 0$$
; $Q_{a7} = 66.556 \text{ kN (C)}$;

$$Q_{a9} = 63 \text{ kN (C)}; Q_{a10} = Q_{a11} = Q_{a12} = 18 \text{ kN (C)}$$

8.7
$$\mathbf{d} = \begin{bmatrix} -0.011755 \\ 0.011755 \end{bmatrix} \text{rad}$$

$$\mathbf{Q}_1 = \begin{bmatrix} 13.758 \text{ k} \\ 36.56 \text{ k-in.} \\ 487.97 \text{ k-in.} \\ 8.7422 \text{ k} \\ -36.56 \text{ k-in.} \\ -36.56 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_2 = \begin{bmatrix} 8.7422 \text{ k} \\ -36.56 \text{ k-in.} \\ 36.56 \text{ k-in.} \\ 13.758 \text{ k} \\ 36.56 \text{ k-in.} \\ -487.97 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 13.758 \text{ k} \\ 36.56 \text{ k-in.} \\ 487.97 \text{ k-in.} \\ 17.484 \text{ k} \\ 13.758 \text{ k} \\ -487.97 \text{ k-in.} \\ -36.56 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{d} = \begin{bmatrix} -3.4115 \text{ in.} \\ 0.038485 \text{ rad} \\ 0.02126 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_1 = \begin{bmatrix} 46.509 \text{ k} \\ -18.507 \text{ k-in.} \\ 8,177.2 \text{ k-in.} \\ -46.509 \text{ k} \\ 18.507 \text{ k-in.} \\ -1,479.9 \text{ k-in.} \end{bmatrix} \quad \mathbf{Q}_2 = \begin{bmatrix} -13.491 \text{ k} \\ 20.1 \text{ k-in.} \\ -18.508 \text{ k-in.} \\ 13.491 \text{ k} \\ -20.1 \text{ k-in.} \\ -3,219.4 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 46.509 \text{ k} \\ -8,177.2 \text{ k-in.} \\ -18.507 \text{ k-in.} \\ 13.491 \text{ k} \\ -20.1 \text{ k-in.} \\ -3,219.4 \text{ k-in.} \end{bmatrix}$$

8.11
$$\mathbf{d} = \begin{bmatrix} -0.77317 \text{ in.} \\ 0.011346 \text{ rad} \\ -0.0032328 \text{ rad} \\ -4.529 \text{ in.} \\ 0.0092457 \text{ rad} \\ -0.017808 \text{ rad} \end{bmatrix}$$

$$\mathbf{Q}_1 = \left[\begin{array}{c} 7.5755 \text{ k} \\ -14.969 \text{ k-in.} \\ 2,746.4 \text{ k-in.} \\ -7.5755 \text{ k} \\ 14.969 \text{ k-in.} \\ -19.229 \text{ k-in.} \end{array} \right]$$

$$\mathbf{Q}_2 = \begin{bmatrix} 7.5755 \text{ k} \\ 19.229 \text{ k-in.} \\ 14.969 \text{ k-in.} \\ 22.425 \text{ k} \\ -19.229 \text{ k-in.} \\ 12.198 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{Q}_3 = \begin{bmatrix} 82.425 \text{ k} \\ -12.198 \text{ k-in.} \\ 18,854 \text{ k-in.} \\ -22.425 \text{ k} \\ 12.198 \text{ k-in.} \\ 19.228 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 7.5755 \text{ k} \\ -14.969 \text{ k-in.} \\ 2,746.4 \text{ k-in.} \\ 82.425 \text{ k} \\ -12.198 \text{ k-in.} \\ 18,854 \text{ k-in.} \end{bmatrix}$$

8.15
$$\mathbf{d} = \begin{bmatrix} -0.06273 \text{ in.} \\ 0.03588 \text{ in.} \\ -0.1942 \text{ in.} \\ -0.4836 \text{ rad} \\ 0.001013 \text{ rad} \\ 0.3067 \text{ rad} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} -3.818 \text{ k} \\ -5.406 \text{ k} \\ -6.013 \text{ k} \\ -600.5 \text{ k-in.} \\ -0.5053 \text{ k-in.} \\ 381.5 \text{ k-in.} \\ 11.81 \text{ k} \\ 5.968 \text{ k} \\ 0.01179 \text{ k} \\ 301.5 \text{ k-in.} \\ -2.204 \text{ k-in.} \\ 477.2 \text{ k-in.} \\ -7.996 \text{ k} \\ -0.562 \text{ k} \\ 6.001 \text{ k} \\ 193.9 \text{ k-in.} \\ -1.143 \text{ k-in.} \\ -215.9 \text{ k-in.} \end{bmatrix}$$

$$\mathbf{R} = \begin{bmatrix} 11.45 \text{ k} \\ 61.97 \text{ k} \\ -4.62 \text{ k} \\ -1,378 \text{ k-in.} \\ -5.934 \text{ k-in.} \\ -2,021 \text{ k-in.} \\ -9.255 \text{ k} \\ 58.03 \text{ k} \\ -14.6 \text{ k} \\ -2,572 \text{ k-in.} \\ -5.934 \text{ k-in.} \\ 1,758 \text{ k-in.} \\ -11.46 \text{ k} \\ 61.97 \text{ k} \\ 4.62 \text{ k} \\ 1,378 \text{ k-in.} \\ -5.947 \text{ k-in.} \\ 2,024 \text{ k-in.} \\ 9.271 \text{ k} \\ 58.03 \text{ k} \\ 14.6 \text{ k} \\ 2,572 \text{ k-in.} \\ -5.947 \text{ k-in.} \\ -1,761 \text{ k-in.} \\ -1,761 \text{ k-in.} \end{bmatrix}$$

Chapter 9

9.1
$$\mathbf{d} = \begin{bmatrix} 0.063295 \\ -0.42908 \end{bmatrix}$$
 in.
 $Q_{a1} = 30.593 \text{ k (T)}; \ Q_{a2} = 122.96 \text{ k (C)};$
 $Q_{a3} = 24.343 \text{ k (T)}$

$$\mathbf{R} = \begin{bmatrix} 73.777 \\ 98.369 \\ 6.816 \\ -23.369 \\ -30.593 \\ 0 \end{bmatrix} \mathbf{k}$$

9.3 See answer to Problem 7.19.

9.11
$$FS_b = \frac{15W}{33}; FM_b = \frac{7WL}{66}; FS_e = \frac{18W}{33}; FM_e = -\frac{5WL}{33}$$

$$\mathbf{d} = \begin{bmatrix} -0.040921 \\ 3.0647 \\ -3.3036 \end{bmatrix} \text{m}$$

9.13
$$d_1 = 6$$
; $d_2 = -11$; $d_3 = 9$

10.1 (a)
$$P \cong \left(\frac{2EA\sin^2\theta}{L}\right)\delta$$

(b)
$$P = 2EA \left[\sin \theta + \left(\frac{\delta}{L} \right) \right] \left[\frac{\sqrt{1 + \left(\frac{\delta}{L} \right)^2 + 2\left(\frac{\delta}{L} \right) \sin \theta} - 1}{\sqrt{1 + \left(\frac{\delta}{L} \right)^2 + 2\left(\frac{\delta}{L} \right) \sin \theta}} \right]$$

10.3
$$\mathbf{d} = \begin{bmatrix} -0.23233 \\ -1.0581 \end{bmatrix} \mathbf{m}$$

$$Q_{a1} = 1,827.2 \text{ kN (C)}; \ Q_{a2} = 2,152.7 \text{ kN (C)};$$

$$\mathbf{R} = \begin{bmatrix} 1,624.2\\837.11\\-1,624.2\\1,412.9 \end{bmatrix} kN$$

10.5
$$\mathbf{d} = \begin{bmatrix} -0.040921 \\ 3.0647 \\ -3.3036 \end{bmatrix}$$
m

$$Q_{a1} = 859.34 \text{ kN (C)}; \ Q_{a2} = 1,032.5 \text{ kN (T)};$$

$$Q_{a3} = 1,122.5 \text{ kN (C)}$$

$$\mathbf{R} = \begin{bmatrix} -0.013871 \\ -572.3 \\ 722.27 \end{bmatrix} \text{kN}$$