

PROCEDURE HOW TO LOGIN ON THE PMDT SOFTWARE IN ACC EQUIPMENT ROOM ON EITHER LOCALIZER OR GLIDE PATH

1. CONNECT USB CABLE BETWEEN RSCU AND PMDT
2. LEFT CLK ON PMDT ICON . THIS OPENS A NEW WINDOW
3. ON THE WINDOW MENU BAR LEFT CLK ON
SYSTEM>>CONNECT>>RCSU>>SERIAL/USB
4. ON THE LOGIN WINDOW OBTAINED, ENTER USER ID.....
PASSWORD.....
5. CLK OK
6. THIS GIVES YOU A NEW WINDOW AS FOLLOWS:
✓ 2240 RSCU
✓ RUNWAY 14
✓ LOCALIZER
✓ GLIDESLOPE
7. RIGHT CLK ON EITHER **LOCALIZER** OR **GLIDESLOPE**, DEPENDING ON
WHICH ONE YOU WANT TO CONNECT
8. YOU GET "**CONNECT TO LOCALIZER 14**", LEFT CLK ON IT
9. THIS OPENS THE LOCALIZER WINDOW . LOCALIZER ALREADY
CONNECTED TO PMDT.
10. SAME PROCEDURE APPLIES FOR GLIDESLOPE

HOW TO LOG OUT FROM LOCALIZER OR GLIDESLOPE

1. LEFT CLK ON SYSTEM>> LOG OFF
2. YOU GET WINDOW AS AT 6 ABOVE
3. CLK ON SYSTEM>> LOG OFF
4. CLK ON SYSTEM>> LOG OUT
5. CLK ON EXIT
6. THE PMDT IS NOW DISCONNECTED FROM ILS

Prepared by:

L.Randhay

Station Officer

Date: 27 september 2021