transformer.220L-1	x1_motor.M+-2	earth-1	110N-3	110L-5	COIL--2	earth-9
transformer.220L-1	x1_motor.M+-2	earth-1	110N-3	110L-5	COIL--2	earth-9
transformer.220L-1	x1_motor.M+-2	earth-1	110N-3	110L-5	COIL--2	earth-9
transformer.220L-1	x1_motor.M+-2	earth-1	110N-3	110L-5	COIL--2	earth-9
transformer.220L-1	x1_motor.M+-2	earth-1	110N-3	110L-5	COIL--2	earth-9
transformer.220N-1	x1_motor.M--2	110L-1	earth-2	earth-6	earth-8	vfd.R-1
transformer.220N-1	x1_motor.M--2	110L-1	earth-2	earth-6	earth-8	vfd.R-1
transformer.220N-1	x1_motor.M--2	110L-1	earth-2	earth-6	earth-8	vfd.R-1
transformer.220N-1	x1_motor.M--2	110L-1	earth-2	earth-6	earth-8	vfd.R-1
transformer.220N-1	x1_motor.M--2	110L-1	earth-2	earth-6	earth-8	vfd.R-1
110L_SWITCHED-1	x2_motor.M+-2	110N-1	earth-3	earth-7	COIL+-4	vfd.T-1
110L_SWITCHED-1	x2_motor.M+-2	110N-1	earth-3	earth-7	COIL+-4	vfd.T-1
110L_SWITCHED-1	x2_motor.M+-2	110N-1	earth-3	earth-7	COIL+-4	vfd.T-1
110L_SWITCHED-1	x2_motor.M+-2	110N-1	earth-3	earth-7	COIL+-4	vfd.T-1
110L_SWITCHED-1	x2_motor.M+-2	110N-1	earth-3	earth-7	COIL+-4	vfd.T-1
110N_SWITCHED-1	x2_motor.M--2	110L-2	110N-4	COIL+-1	spindle.u-2	VFD_FWD-1
110N_SWITCHED-1	x2_motor.M--2	110L-2	110N-4	COIL+-1	spindle.u-2	VFD_FWD-1
110N_SWITCHED-1	x2_motor.M--2	110L-2	110N-4	COIL+-1	spindle.u-2	VFD_FWD-1
110N_SWITCHED-1	x2_motor.M--2	110L-2	110N-4	COIL+-1	spindle.u-2	VFD_FWD-1
110N_SWITCHED-1	x2_motor.M--2	110L-2	110N-4	COIL+-1	spindle.u-2	VFD_FWD-1
110L_SWITCHED-2	DRIVER_48V-1	110N-2	110L-4	COIL+-2	spindle.v-2	VFD_REV-1
110L_SWITCHED-2	DRIVER_48V-1	110N-2	110L-4	COIL+-2	spindle.v-2	VFD_REV-1
110L_SWITCHED-2	DRIVER_48V-1	110N-2	110L-4	COIL+-2	spindle.v-2	VFD_REV-1
110L_SWITCHED-2	DRIVER_48V-1	110N-2	110L-4	COIL+-2	spindle.v-2	VFD_REV-1
110L_SWITCHED-2	DRIVER_48V-1	110N-2	110L-4	COIL+-2	spindle.v-2	VFD_REV-1
110N_SWITCHED-2	DRIVER_GND-5	110L-3	110N-5	COIL--1	spindle.w-2	COIL+-5
110N_SWITCHED-2	DRIVER_GND-5	110L-3	110N-5	COIL--1	spindle.w-2	COIL+-5
110N_SWITCHED-2	DRIVER_GND-5	110L-3	110N-5	COIL--1	spindle.w-2	COIL+-5
110N_SWITCHED-2	DRIVER_GND-5	110L-3	110N-5	COIL--1	spindle.w-2	COIL+-5
110N_SWITCHED-2	DRIVER_GND-5	110L-3	110N-5	COIL--1	spindle.w-2	COIL+-5