



Petrel Geophysics Module 5: Condition input data for seismic well tie




Lesson 1: Checkshot data loading





Load checkshot data (1)

- 1. Right-click the **Wells** folder and click *Import* (on selection) to open the **Import file** dialog box.
- 2. Set Files of type to *Checkshots* format (ASCII) (*.*).
- 3. Select one or more files to import and click *Open*.



input ⊿ AA □

G 🚳


Import (on selection) . . .

Export object



Load checkshot data (2)


- 4. From the header info in the lower section of the dialog box, insert the parameters into the spreadsheet at the top of the dialog box.
- 5. If the Well name is not included in the input checkshot file, assign and verify *Connect to trace* to the correct well.





Load checkshot data (3)

- 6. Select time and depth datum.
- 7. Click *OK* to complete the checkshot data loading.






Load checkshots: Errors


Checkshot data is imported incorrectly when the input file contains positive time values. Change the column to TWT and check *Negate time values*.

X-Coord	Y-Coord	Z	TWT	MD
1599743.87	-172747.82	0.00	0.00	95.00
1599743.09	-172748.18	-100.00	39.71	195.01
1599743.02	-172748.21	-105.00	41.70	200.01
1599738.12	-172747.07	-304.90	119.30	399.98
1599732.30	-172747.23	-704.80	268.00	799.9
etc				

TWT must be negative!











QC checkshots (1)

Right-click checkshots in the Global well logs folder and open the spreadsheet.

Check for negative velocities and TWT.




NOTE: It is important to always QC the loaded data. In this example, negative time and velocity values reflect errors in the checkshot loading.





QC checkshots


Correctly loaded checkshot survey parameters – TWT, TVDSS, and velocities – are positive numbers.





Edit checkshot data (1)


- 1. In a **Function** window, display the Interval velocity attribute of checkshots against Z (or TWT). Use a well filter to display individual checkshot surveys.
- 2. Use one of the filter icons from the **Window** toolbar and select the outliers. The automatically created filter is stored in **Filters** folder in the **Input** pane.





Edit checkshot data (2)

- 3. Click the Select using freehand draw icon and paint a closed area in the **Function** window. Make sure that the filter polygon contains some bad points.
- 4. In the Checkshots spreadsheet, click the Delete selected row(s) in the table icon to remove the rows, then click Apply to make the change in the checkshot data.
- 5. Check the other wells for outliers.






Time-depth relationships

The **Time** tab in the *Wells* folder **Settings** dialog box contains a list of available sources for the time-depth relationship for all wells.

If you select more than one object, the list is used in a hierarchical order.





Exercises

