
Master Clock Time
Slave Clock Time
t1
Sync
t2
tms= t2-t1
Follow_Up
t3
Delay_Req
tsm= t4-t3
t4
Delay_Resp