Version: 1.01.11.03

Date: 22 Mar 2011

New Features

N/A

Bugs Fixed

- 1. Insufficient waiting time for reply from N5100.XP causes "Cold Start" and "Clear Card DB" command fail.
- 2. After sending command to N5100.XP, occasionally will not wait for reply from N5100.XP causes wrong feedback to P1.

Modification

N/A

Compatibility List

• P1 Server 3.11d.11.04