Version: 01.05.16.02 Latest Date: 02 February 2016

New Features
1. None

Bugs Fixed

1. Polling rate is improved.

Modification

1. None

Compatibility List

DRB version "DRB_05_PCB" and above
 L3800 Version: 1.07.14.06 and above

Version: 01.04.15.11 Date: 04 November 2015

New Features

- 2. Selecting of the LED and Buzzer outputs type to "active high" and "active low" by using JP4 Pin7&Pin8 (Open=Default=Active low)
- 3. Choose card flash timeout of 3 seconds by using JP4 pin5,pin6 (Open=Default=Timeout enabled)

Bugs Fixed

- 2. None Modification
- 2. None

Compatibility List

3. DRB version "DRB_05_PCB" and above

4 L3800 Version: 1 07 14 06 and above

Version: 01.03.15.09

WIE485 Release notes

Date: 10 September 2015

New Features

4. None

Bugs Fixed

- 3. Reader HOT unplug problem solved.
- 4. Local interrupt enable-Disable pairs improved.
- 5. OSDP packet descriptor write pointer control improved.

Modification

3. None

Compatibility List

- 5. DRB version "DRB 05 PCB" and above
- 6. L3800 Version: 1.07.14.06 and above

Version: 01.02.15.07 Date: 27 July 2015

New Features

- 5. "OSDP_COMSET" and "OSDP_ID" commands are added
- 6. Can see the firmware version on system start up on COM1

Bugs Fixed

6. None

Modification

4. None

Compatibility List

- 7. DRB version "DRB_05_PCB" and above
- 8 L3800 Version: 1 07 14 06 and above

WIE485 Release notes

Version: 01.01.15.01 Date: 27 January 2015

New Features

1. Initial Release

Bugs Fixed

7. None

Modification

5. None

Compatibility List

9. DRB version "DRB_05_PCB" and above 10. L3800 Version: 1.07.14.06 and above