Version: 3.14f.19.09 LATEST

Date: 25 Sep 2019

New Features

1. Support HIO DDS Event Relay Setting (i.e. trigger relay upon event code received via DDS) feature.

Bugs Fixed

- 1. Read-Only user not able to close form under Controller->HIO->Edit Alarm Zone.
- 2. Wrong validation checking for HIO after Alarm Zone is deleted.
- 3. Rectify label for Wiegand listing grid report.
- 4. Skip GetNode command from serial model controllers.

Modification

N/A

- P1 Server 3.15f.19.09
- P1 Report 3.11f.19.09

Version: 3.14e.19.08 Date: 19 Aug 2019

New Features

- 1. Support N6200 and N6400 with Card Expiry time (hh:mm).
- 2. Support VMS QR Code integration. Applicable to S3150, N5150, N6200 and N6400 only.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.15e.19.08
- P1 Report 3.11e.19.08

Version: 3.14d.19.07 Date: 2 Jul 2019

New Features

1. Support NE6800 with DDS, SR100/SR 200 and Wiegand 64bits.

Bugs Fixed

- 1. Not able to delete Holiday record when upgrade from older version of P1.
- 2. Incorrect Reader Name shown for transaction "Incorrect Card Bits Format" for NE4800 and NE6800.
- 3. Blank screen shown when "Dock All to Main Screen" is clicked while undocked screens are minimized.

Modification

N/A

- P1 Server 3.15d.19.07
- P1 Report 3.11d.19.07

Version: 3.14c.19.04 Date: 24 Apr 2019

New Features

1. Added support for NE6800 (note that DDS, SR100/SR 200 and Wiegand 64bits are not supported yet).

Bugs Fixed

- 1. Lift cards not sent to lift controllers.
- 2. Ensure card no. which is read from "Scan From Writer" will be pad with 0 in front if less than 10 digits.

Modification

N/A

- P1 Server 3.15c.19.04
- P1 Report 3.11c.19.04

Version: 3.14b.19.03 Date: 22 Mar 2019

New Features

- 1. Support clustering for holiday (under Cluster module).
- 2. Card Expiry now supports time (hh:mm). Applicable to N5150 and S3150 only.

Bugs Fixed

- 1. Incorrect UI showed when controller model is changed, after HIO is selected (under Add Ctrl UI).
- 2. Incorrect value of bits showed when Advance Configuration selected (under Wiegand Group UI).
- 3. Cluster user should have Read Only access to Area module.

Modification

- 1. Column "Is Shared", and "right click->Share" only showed if Cluster module enabled (under View Access Group UI).
- 2. Accessibility of menu (under Menu Control UI) to be showed as the same as in P1 Server to avoid confusion.

- P1 Server 3.15b.19.03
- P1 Report 3.11b.19.03

Version: 3.14a.19.02 Date: 1 Feb 2019

New Features

- 1. Support Area feature (to have different GMT in different places).
- 2. TA export to include OT1.5, OT2.0 and OT3.0 data.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.15a.19.02
- P1 Report 3.11a.19.02

Version: 3.14.19.01 Date: 11 Jan 2019

New Features

- 1. Support Redundancy module.
- 2. Support Cluster module.
- 3. NE4800 supports Smart Reader, DDS and DDS with Heartbeat.
- 4. N5150, N5200, N5400, N6200 and N6400 support DDS with Heartbeat.
- 5. Support Strong Password and Expiry for System User.

Bugs Fixed

N/A

Modification

1. Company logo changed.

- P1 Server 3.15.19.01
- P1 Report 3.11.19.01

Version: 3.13g.17.11 Date: 29 Nov 2017

New Features

N/A

Bugs Fixed

1. Wrong Conversion Type is sent to L3800 when Wiegand Format other than 64 bit is chosen.

Modification

N/A

- P1 Server 3.14g.17.11
- P1 Report 3.10f.17.11

Version: 3.13f.17.11 Date: 23 Nov 2017

New Features

1. Added support for SR100 and SR200 readers for controller model L3800.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.14f.17.11
- P1 Report 3.10f.17.11

Version: 3.13e.17.09 Date: 21 Sep 2017

New Features

1. Support Secure Channel feature for SR100 and SR200 Smart Reader.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.14e.17.09
- P1 Report 3.10e.17.09

Version: 3.13d.17.05 Date: 27 May 2017

New Features

1. Support SR200 Smart Reader.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.14d.17.05
- P1 Report 3.10d.17.05

Version: 3.13c.17.03 Date: 22 Mar 2017

New Features

1. Added Dock All To Main Screen feature to pull back all undock screen.

Bugs Fixed

- 1. Error message pop up when controller's profile is changed.
- 2. Export staff with multiple cards will cause card no. being duplicated in the file.
- 3. Retrieve card info from S3400 model will render card info without appropriate format.

Modification

1. Support Samsung SDK v1.44.

- P1 Server 3.14c.17.03
- P1 Report 3.10c.17.03

Version: 3.13b.16.11 Date: 18 Nov 2016

New Features

- 1. Support Nested Car Park feature (for N5150, N5200, N5400, N6200 and N6400).
- 2. Support controller-based XML server (Dahua integration) (for N5150, N5200, N5400, N6200 and N6400). Note that Dongle is required to activate this feature.

Bugs Fixed

N/A

Modification

N/A

- P1 Server 3.14b.16.11
- P1 Report 3.10b.16.11

Version: 3.13a.16.10 Date: 27 Oct 2016

New Features

N/A

Bugs Fixed

N/A

Modification

1. Samsung brand become standard in CIM module. HeiTel is removed.

- P1 Server 3.14a.16.10
- P1 Report 3.10a.16.10

Version: 3.13.16.08 Date: 20 Sep 2016

New Features

1. Support N6200 and N6400.

Bugs Fixed

1. Wrong information showed when controller setting is retrieved.

Modification

N/A

- P1 Server 3.14.16.08
- P1 Report 3.10.16.08

Version: 3.12.16.02 Date: 2 Feb 2016

New Features

N/A

Bugs Fixed

1. Under Floor Plan, icon for door 3 and door 4 are not updated when door sensor and push button are not defined for door 1 and door 2.

Modification

N/A

- P1 Server 3.13.16.02
- P1 Report 3.09.16.02