Version: 3.15f.19.09 LATEST

Date: 25 Sep 2019

#### **New Features**

1. Support HIO DDS Event Relay Setting (i.e. trigger relay upon event code received via DDS) feature.

## **Bugs Fixed**

- 1. Read-Only user not able to close form under Controller->HIO->Edit Alarm Zone.
- 2. Wrong validation checking for HIO after Alarm Zone is deleted.
- 3. Rectify label for Wiegand listing grid report.
- 4. Skip GetNode command from serial model controllers.

## Modification

1. Speed up first time loading of P1 (as compared to v3.15e.19.08).

- P1 Client 3.14f.19.09
- P1 Report 3.11f.19.09
- Active Engine 1.17c.19.04
- P1 Guardian 1.04.10.02
- XSocket 2.02.19.08
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03
- EVIM 1.00.19.07

Version: 3.15e.19.08 Date: 19 Aug 2019

# New Features

- 1. Support N6200 and N6400 with Card Expiry time (hh:mm).
- 2. Support VMS QR Code integration. Applicable to S3150, N5150, N6200 and N6400 only.

**Bugs Fixed** 

N/A

## Modification

N/A

- P1 Client 3.14e.19.08
- P1 Report 3.11e.19.08
- Active Engine 1.17c.19.04
- P1 Guardian 1.04.10.02
- XSocket 2.02.19.08
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03
- EVIM 1.00.19.07

Version: 3.15d.19.07 Date: 2 Jul 2019

#### **New Features**

- 1. Support NE6800 with DDS, SR100/SR 200 and Wiegand 64bits.
- 2. Support EVIM (Event Insertion Module). Require dongle.

# **Bugs Fixed**

- 1. Not able to delete Holiday record when upgrade from older version of P1.
- 2. For VPS, incorrect access info of card being sent to controllers which are using Access Group.
- 3. Incorrect Reader Name shown for transaction "Incorrect Card Bits Format" for NE4800 and NE6800.
- 4. Blank screen shown when "Dock All to Main Screen" is clicked while undocked screens are minimized.

#### Modification

1. Restore speed of Login and Logout.

- P1 Client 3.14d.19.07
- P1 Report 3.11d.19.07
- Active Engine 1.17c.19.04
- P1 Guardian 1.04.10.02
- XSocket 2.01.19.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03
- EVIM 1.00.19.07

Version: 3.15c.19.04 Date: 24 Apr 2019

## **New Features**

1. Added support for NE6800 (note that DDS, SR100/SR 200 and Wiegand 64bits are not supported yet).

## **Bugs Fixed**

- 1. Lift cards not sent to lift controllers.
- 2. Ensure card no. which is read from "Scan From Writer" will be pad with 0 in front if less than 10 digits.
- 3. "Clear template data" not executed if Cold Start is selected under Send/Retrieve UI.

## Modification

N/A

- P1 Client 3.14c.19.04
- P1 Report 3.11c.19.04
- Active Engine 1.17c.19.04
- P1 Guardian 1.04.10.02
- XSocket 2.01.19.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.15b.19.03 Date: 22 Mar 2019

#### **New Features**

- 1. Support clustering for holiday (under Cluster module).
- 2. No. of Active Engine is now configurable (via Preferences UI).
- 3. Card Expiry now supports time (hh:mm). Applicable to N5150 and S3150 only.

#### **Bugs Fixed**

- 1. Incorrect UI showed when controller model is changed, after HIO is selected (under Add Ctrl UI).
- 2. Incorrect value of bits showed when Advance Configuration selected (under Wiegand Group UI).
- 3. Error pop up when invalid data sent to Port 2205.
- 4. IP Address of Local Node not updated (under Redundancy module) when database are copied to another machine for troubleshooting purpose.

#### Modification

- 1. Column "Is Shared", and "right click->Share" only showed if Cluster module enabled (under View Access Group UI).
- 2. Added "Cancel" button for Send Card command.

- P1 Client 3.14b.19.03
- P1 Report 3.11b.19.03
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 2.01.19.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.15a.19.02 Date: 1 Feb 2019

## **New Features**

- 1. Support Area feature (to have different GMT in different places). Require dongle.
- 2. TA export to include OT1.5, OT2.0 and OT3.0 data.

# **Bugs Fixed**

N/A

# Modification

N/A

- P1 Client 3.14a.19.02
- P1 Report 3.11a.19.02
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 2.00.19.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.15.19.01 Date: 11 Jan 2019

#### **New Features**

- 1. Support Redundancy module. Require dongle.
- 2. Support Cluster module. Require dongle.
- 3. NE4800 supports Smart Reader.
- 4. NE4800 supports DDS and DDS with Heartbeat. Require dongle.
- 5. N5150, N5200, N5400, N6200 and N6400 support DDS with Heartbeat. Require dongle.
- 6. Support Strong Password and Expiry for System User.

# **Bugs Fixed**

N/A

#### Modification

- 1. Company logo changed.
- 2. Email/SMS Notification based on specific alarm transaction codes (configurable via Platform1.ini).
- 3. Auto Posting of TA (configurable via Platform1.ini).
- 4. Support Door Operation commands of xSocket.

- P1 Client 3.14.19.01
- P1 Report 3.11.19.01
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 2.00.19.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14g.17.11 Date: 4 Dec 2017

## **New Features**

N/A

# **Bugs Fixed**

- 1. Software Digit is not sent to L3800 when it is changed under Preferences.
- 2. Wrong Conversion Type is sent to L3800 when Wiegand Format other than 64 bit is chosen.

## Modification

N/A

- P1 Client 3.13g.17.11
- P1 Report 3.10f.17.11
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 1.07c.17.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14f.17.11 Date: 23 Nov 2017

# New Features

1. Added support for SR100 and SR200 readers for controller model L3800.

Bugs Fixed

N/A

Modification

N/A

- P1 Client 3.13f.17.11
- P1 Report 3.10f.17.11
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 1.07c.17.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14e.17.09 Date: 21 Sep 2017

# New Features

1. Support Secure Channel feature for SR100 and SR200 Smart Reader.

**Bugs Fixed** 

N/A

Modification

N/A

- P1 Client 3.13e.17.09
- P1 Report 3.10e.17.09
- Active Engine 1.17b.17.09
- P1 Guardian 1.04.10.02
- XSocket 1.07c.17.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14d.17.05 Date: 27 May 2017

# New Features

1. Support SR200 Smart Reader.

**Bugs Fixed** 

N/A

Modification

N/A

- P1 Client 3.13d.17.05
- P1 Report 3.10d.17.05
- Active Engine 1.17.16.08
- P1 Guardian 1.04.10.02
- XSocket 1.07c.17.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14c.17.03 Date: 22 Mar 2017

#### **New Features**

- 1. Support Parallel Sending for Add, Update and Delete Card command.
- 2. Added Dock All To Main Screen feature to pull back all undock screen.

## **Bugs Fixed**

- 1. Backup fail to complete when transaction files are selected.
- 2. Error message pop up when controller's profile is changed.
- 3. Export staff with multiple cards will cause card no. being duplicated in the file.
- 4. Retrieve card info from S3400 model will render card info without appropriate format.
- 5. Card generated via Batch Card feature will cause wrong info being sent over to controller.
- 6. Access Group added or deleted via Card Edit feature should trigger card sending process but it did not.

#### Modification

- 1. Support 3G modem for SMS notification.
- 2. Support Samsung SDK v1.44.

- P1 Client 3.13c.17.03
- P1 Report 3.10c.17.03
- Active Engine 1.17.16.08
- P1 Guardian 1.04.10.02
- XSocket 1.07c.17.03
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14b.16.11 Date: 18 Nov 2016

## **New Features**

- 1. Support Nested Car Park feature (for N5150, N5200, N5400, N6200 and N6400).
- 2. Support controller-based XML server (Dahua integration) (for N5150, N5200, N5400, N6200 and N6400). Note that Dongle is required to activate this feature.

**Bugs Fixed** 

N/A

Modification

N/A

- P1 Client 3.13b.16.11
- P1 Report 3.10b.16.11
- Active Engine 1.17.16.08
- P1 Guardian 1.04.10.02
- XSocket 1.07.16.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14a.16.10 Date: 27 Oct 2016

New Features

N/A

Bugs Fixed

N/A

# Modification

1. Samsung brand become standard in CIM module. HeiTel is removed.

- P1 Client 3.13a.16.10
- P1 Report 3.10a.16.10
- Active Engine 1.17.16.08
- P1 Guardian 1.04.10.02
- XSocket 1.07.16.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.14.16.08 Date: 20 Sep 2016

# New Features

1. Support N6200 and N6400.

# **Bugs Fixed**

1. Wrong information showed when controller setting is retrieved.

## Modification

N/A

- P1 Client 3.13.16.08
- P1 Report 3.10.16.08
- Active Engine 1.17.16.08
- P1 Guardian 1.04.10.02
- XSocket 1.07.16.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.13a.16.05 Date: 6 May 2016

#### **New Features**

N/A

## **Bugs Fixed**

- 1. Sending "Get Feature" command to conventional controllers will appear Fail in Send Result form.
- 2. Sending "Get Feature" command to HIO will cause P1 to stuck in the midst of the process.
- 3. Retrieve Floor Access Level from L3800 will show wrong information.
- 4. Auto import staffs feature does not import data from ".csv" file.
- 5. Reader type label "HADP/OSDP" changed to "HADP" for L3800.
- 6. TA Export causes "Out of memory" when a huge amount of data need to be exported.
- 7. For HCB controllers, "Use Built-In Tamper" and "Lockdown during Tampered" features under Controller->Reader tab should be hidden.

## Modification

N/A

- P1 Client 3.12.16.02
- P1 Report 3.09.16.02
- Active Engine 1.16.15.11
- P1 Guardian 1.04.10.02
- XSocket 1.07.16.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03

Version: 3.13.16.02 Date: 2 Feb 2016

#### **New Features**

N/A

# **Bugs Fixed**

- 1. Under Floor Plan, icon for door 3 and door 4 are not updated when door sensor and push button are not defined for door 1 and door 2.
- 2. Fail to detect multiple IP Address assigned to a single network adapter.

## Modification

N/A

- P1 Client 3.12.16.02
- P1 Report 3.09.16.02
- Active Engine 1.16.15.11
- P1 Guardian 1.04.10.02
- XSocket 1.07.16.01
- Transaction Exporter 1.06.11.01
- Transaction Server 1.07a.16.01
- XParser 1.01.11.03