Connector	Pin	Function	State		Function Minor
Arm Han108	1	L	42 ohm		JT1 REF+ R1
Arm Han108	2	<u>)</u>			JT1 REF- R3
Arm Han108	3	}	Open		JT1 REF SHIELD
Arm Han108	4	ļ	113 ohm		JT1 COS+ S1
Arm Han108	5	JT1 REF+ R1			JT1 COS- S3
Arm Han108	ϵ		Open		JT1 COS SHIELD
Arm Han108	7	,	113 ohm		JT1 SIN+ S2
Arm Han108	8	3			JT1 SIN- S4
Arm Han108	9)	Open		JT1 SIN SHIELD
Arm Han108	10) NC	NC		
Arm Han108	11	. NC	NC		
Arm Han108	12		DIODE		BRAKE+
Arm Han108	13	PWR BRK+			BRAKE-
Arm Han108	14	ļ	SHORT	?	JT1 THS
Arm Han108	15	;		?	JT1 THS
Arm Han108	16	5	3 ohm all		JT1 U
Arm Han108	17	7			JT1 V
Arm Han108	18	3			JT1 W
Arm Han108	19)	46 ohm		JT2 REF+ R1
Arm Han108	20)			JT2 REF- R3
Arm Han108	21	JT1 THS	Open		JT2 REF SHIELD
Arm Han108	22	<u> </u>	116 ohm		JT2 COS+ S1
Arm Han108	23	}			JT2 COS- S3
Arm Han108	24	ļ.	Open		JT2 COS SHIELD
Arm Han108	25	;	116 ohm		JT2 SIN+ S2
Arm Han108	26	j .			JT2 SIN- S4
Arm Han108	27	,	Open		JT2 SIN SHIELD
Arm Han108	28	B NC	NC		
Arm Han108	29) NC	NC		
Arm Han108	30) NC	NC		
Arm Han108	31	. NC	NC		
Arm Han108	32	2	SHORT	?	JT2 THS
Arm Han108	33	}		?	JT2 THS
Arm Han108	34	ļ	3 ohm all		JT2 U
Arm Han108	35				JT2 V
Arm Han108	36				JT2 W
Arm Han108	37	,	109 ohm		JT3 REF+ R1
Arm Han108	38	3			JT3 REF- R3
Arm Han108	39	JT2 THS	Open		JT3 REF SHIELD
Arm Han108	40)	105 ohm		JT3 COS+ S1
Arm Han108	41	L			JT3 COS- S3
Arm Han108	42	<u>)</u>	Open		JT3 COS SHIELD
Arm Han108	43	}	105 ohm		JT3 SIN+ S2
Arm Han108	44	ļ			JT3 SIN- S4
Arm Han108	45	; ;	Open		JT3 SIN SHIELD
Arm Han108	46	6 NC	NC		
Arm Han108	47		NC		
Arm Han108	48	B NC	NC		
Arm Han108	49) NC	NC		

Arm Han108	50	NC	NC		
Arm Han108	51	NC	NC		
Arm Han108	52		4 ohm all		JT3 U
Arm Han108	53	JT3 U			JT3 V
Arm Han108	54				JT3 W
Arm Han108	55		44 ohm		JT4 REF+ R1
Arm Han108	56				JT4 REF- R3
Arm Han108	57		Open		JT4 REF SHIELD
Arm Han108	58		92 ohm		JT4 COS+ S1
Arm Han108	59	JT4 REF+ R1			JT4 COS- S3
Arm Han108	60		Open		JT4 COS SHIELD
Arm Han108	61		92 ohm		JT4 SIN+ S2
Arm Han108	62				JT4 SIN- S4
Arm Han108	63		Open		JT4 SIN SHIELD
Arm Han108	64	NC	NC		
Arm Han108	65	NC	NC		
Arm Han108	66	NC	NC		
Arm Han108	67	NC	NC		
Arm Han108	68	NC	NC		
Arm Han108	69	NC	NC		
Arm Han108	70		21 ohm all		JT4 U
Arm Han108	71	JT4 U			JT4 V
Arm Han108	72				JT4 W
Arm Han108	73		44 ohm		JT5 REF+ R1
Arm Han108	74				JT5 REF- R3
Arm Han108	75		Open		JT5 REF SHIELD
Arm Han108	76		92 ohm		JT5 COS+ S1
Arm Han108	77	JT5 REF+ R1			JT5 COS- S3
Arm Han108	78		Open		JT5 COS SHIELD
Arm Han108	79		92 ohm		JT5 SIN+ S2
Arm Han108	80				JT5 SIN- S4
Arm Han108	81		Open		JT5 SIN SHIELD
Arm Han108	82	NC	NC		
Arm Han108	83	NC	NC		
Arm Han108	84			?	PB RLS
Arm Han108	85	BRK		?	BRE
Arm Han108	86			?	PWR
Arm Han108	87	NC	NC	_	
Arm Han108	88		21 ohm all		JT5 U
Arm Han108	89	JT5 U			JT5 V
Arm Han108	90				JT5 W
Arm Han108	91		44 ohm		JT6 REF+ R1
Arm Han108	92				JT6 REF- R3
Arm Han108	93		Open		JT6 REF SHIELD
Arm Han108	94		91 ohm		JT6 COS+ S1
Arm Han108	95	JT6 REF+ R1			JT6 COS- S3
Arm Han108	96		Open		JT6 COS SHIELD
Arm Han108	97		91 ohm		JT6 SIN+ S2
Arm Han108	98				JT6 SIN- S4
Arm Han108	99		Open		JT6 SIN SHIELD

Arm Han108	100	NC	NC	
Arm Han108	101	NC	NC	
Arm Han108	102		95 ohm	
Arm Han108	103	VALVE1+		0
Arm Han108	104		95 ohm	
Arm Han108	105	NC	NC	
Arm Han108	106		21 ohm all	
Arm Han108	107	JT6 U		
Arm Han108	108			

JT6 U JT6 V JT6 W

	Connector			
1	Cont Han72	LS1 Limit+	10	Cont Han72
2	Cont Han72	LOT EITHE.	11	Cont Han72
3	Cont Han72		12	Cont Han72
4	Cont Han72		23	Cont Han72
5	Cont Han72		24	Cont Han72
6	Cont Han72		35	Cont Han72
7	Cont Han72		36	Cont Han72
8	Cont Han72	LS2 Limit-	46	Cont Han72
9	Cont Han72		47	Cont Han72
•	30		48	Cont Han72
			59	Cont Han72
16	Cont HanK6/36			Cont Han72
22	Cont HanK6/36		70	Cont Han72
14	Cont HanK6/36		71	Cont Han72
15	Cont HanK6/36		72	Cont Han72
1	Cont HanK6/36		7	Cont HanK6/36
2	Cont HanK6/36		8	Cont HanK6/36
3	Cont HanK6/36		9	Cont HanK6/36
13	Cont Han72		10	Cont HanK6/36
14	Cont Han72		11	Cont HanK6/36
15	Cont Han72		12	Cont HanK6/36
16	Cont Han72		13	Cont HanK6/36
17	Cont Han72		17	Cont HanK6/36
18	Cont Han72		18	Cont HanK6/36
19	Cont Han72		19	Cont HanK6/36
20	Cont Han72		28	Cont HanK6/36
21	Cont Han72	CLAMP1+	34	Cont HanK6/36
		0V2	40	Cont HanK6/36
		CLAMP1-	46	Cont HanK6/36
		JT3 THS	26	Cont HanK6/36
		JT3 THS	27	Cont HanK6/36
20	Cont HanK6/36	JT4 THS	32	Cont HanK6/36
21	Cont HanK6/36	JT4 THS	33	Cont HanK6/36
4	Cont HanK6/36	JT5 THS	38	Cont HanK6/36
5	Cont HanK6/36	JT5 THS	39	Cont HanK6/36
6	Cont HanK6/36	JT6 THS	44	Cont HanK6/36
25	Cont Han72	JT6 THS	45	Cont HanK6/36
26	Cont Han72			
27	Cont Han72			
28	Cont Han72			
29	Cont Han72			
30	Cont Han72			
31	Cont Han72			
32	Cont Han72			
33	Cont Han72			

- 23 Cont HanK6/36
- 24 Cont HanK6/36
- 25 Cont HanK6/36
- 37 Cont Han72
- 38 Cont Han72
- 39 Cont Han72
- 40 Cont Han72
- 41 Cont Han72
- 42 Cont Han72
- 43 Cont Han72
- 44 Cont Han72
- 45 Cont Han72

- 29 Cont HanK6/36
- 30 Cont HanK6/36
- 31 Cont HanK6/36
- 49 Cont Han72
- 50 Cont Han72
- 51 Cont Han72
- 52 Cont Han72
- 53 Cont Han72
- 54 Cont Han72
- 55 Cont Han72
- 56 Cont Han72
- 57 Cont Han72
- 34 Cont Han72
- 22 Cont Han72
- 58 Cont Han72
- 35 Cont HanK6/36
- 36 Cont HanK6/36
- 37 Cont HanK6/36
- 61 Cont Han72
- 62 Cont Han72
- 63 Cont Han72
- 64 Cont Han72
- 65 Cont Han72
- 66 Cont Han7267 Cont Han72
- 68 Cont Han72
- 69 Cont Han72

- 41 Cont HanK6/36
- 42 Cont HanK6/36
- 43 Cont HanK6/36