Connector	Pin	Function	State	Function Minor
Arm Han108	1		42 ohm	JT1 REF+ R1
Arm Han108	2			JT1 REF- R3
Arm Han108	3		Open	JT1 REF SHIELD
Arm Han108	4		113 ohm	JT1 COS+ S1
Arm Han108	5	JT1 REF+ R1		JT1 COS- S3
Arm Han108	6		Open	JT1 COS SHIELD
Arm Han108	7		113 ohm	JT1 SIN+ S2
Arm Han108	8			JT1 SIN- S4
Arm Han108	9		Open	JT1 SIN SHIELD
Arm Han108	10	NC	NC	
Arm Han108	11	NC	NC	
Arm Han108	12	PWR BRK+	DIODE	BRAKE+
Arm Han108	13	F VVIX DIXIXT		BRAKE-
Arm Han108	14		SHORT	? JT1 THS
Arm Han108	15			? JT1 THS
Arm Han108	16		3 ohm all	JT1 U
Arm Han108	17			JT1 V
Arm Han108	18			JT1 W
Arm Han108	19		46 ohm	JT2 REF+ R1
Arm Han108	20	JT1 THS		JT2 REF- R3
Arm Han108	21	111 1113	Open	JT2 REF SHIELD
Arm Han108	22		116 ohm	JT2 COS+ S1
Arm Han108	23			JT2 COS- S3
Arm Han108	24		Open	JT2 COS SHIELD
Arm Han108	25		116 ohm	JT2 SIN+ S2
Arm Han108	26			JT2 SIN- S4
Arm Han108	27		Open	JT2 SIN SHIELD
Arm Han108	28	NC	NC	
Arm Han108	29	NC	NC	
Arm Han108	30	NC	NC	
Arm Han108	31	NC	NC	

Connector	Pin	Function	State	Function Minor
Arm Han108	32		SHORT	? JT2 THS
Arm Han108	33			? JT2 THS
Arm Han108	34		3 ohm all	JT2 U
Arm Han108	35			JT2 V
Arm Han108	36			JT2 W
Arm Han108	37		109 ohm	JT3 REF+ R1
Arm Han108	38	JT2 THS		JT3 REF- R3
Arm Han108	39	112 1113	Open	JT3 REF SHIELD
Arm Han108	40		105 ohm	JT3 COS+ S1
Arm Han108	41			JT3 COS- S3
Arm Han108	42		Open	JT3 COS SHIELD
Arm Han108	43		105 ohm	JT3 SIN+ S2
Arm Han108	44			JT3 SIN- S4
Arm Han108	45		Open	JT3 SIN SHIELD
Arm Han108	46	NC	NC	
Arm Han108	47	NC	NC	
Arm Han108	48	NC	NC	
Arm Han108	49	NC	NC	
Arm Han108	50	NC	NC	
Arm Han108	51	NC	NC	
Arm Han108	52		4 ohm all	JT3 U
Arm Han108	53	JT3 U		JT3 V
Arm Han108	54			JT3 W
Arm Han108	55		44 ohm	JT4 REF+ R1
Arm Han108	56			JT4 REF- R3
Arm Han108	57		Open	JT4 REF SHIELD
Arm Han108	58		92 ohm	JT4 COS+ S1
Arm Han108	59	JT4 REF+ R1		JT4 COS- S3
Arm Han108	60		Open	JT4 COS SHIELD
Arm Han108	61		92 ohm	JT4 SIN+ S2
Arm Han108	62			JT4 SIN- S4
Arm Han108	63		Open	JT4 SIN SHIELD

Connector	Pin	Function	State		Function Minor
Arm Han108	64	NC	NC		
Arm Han108	65	NC	NC		
Arm Han108	66	NC	NC		
Arm Han108	67	NC	NC		
Arm Han108	68	NC	NC		
Arm Han108	69	NC	NC		
Arm Han108	70		21 ohm all		JT4 U
Arm Han108	71	JT4 U			JT4 V
Arm Han108	72				JT4 W
Arm Han108	73		44 ohm		JT5 REF+ R1
Arm Han108	74				JT5 REF- R3
Arm Han108	75		Open		JT5 REF SHIELD
Arm Han108	76		92 ohm		JT5 COS+ S1
Arm Han108	77	JT5 REF+ R1			JT5 COS- S3
Arm Han108	78		Open		JT5 COS SHIELD
Arm Han108	79		92 ohm		JT5 SIN+ S2
Arm Han108	80				JT5 SIN- S4
Arm Han108	81		Open		JT5 SIN SHIELD
Arm Han108	82	NC	NC		
Arm Han108	83	NC	NC		
Arm Han108	84			?	PB RLS
Arm Han108	85	BRK		?	BRE
Arm Han108	86			?	PWR
Arm Han108	87	NC	NC		
Arm Han108	88		21 ohm all		JT5 U
Arm Han108	89	JT5 U			JT5 V
Arm Han108	90				JT5 W
Arm Han108	91		44 ohm		JT6 REF+ R1
Arm Han108	92				JT6 REF- R3
Arm Han108	93		Open		JT6 REF SHIELD
Arm Han108	94		91 ohm		JT6 COS+ S1
Arm Han108	95	JT6 REF+ R1			JT6 COS- S3
Arm Han108	96		Open		JT6 COS SHIELD
Arm Han108	97		91 ohm		JT6 SIN+ S2
Arm Han108	98				JT6 SIN- S4
Arm Han108	99		Open		JT6 SIN SHIELD

Connector	Pin	Function	State	Function Minor
Arm Han108	100	NC	NC	
Arm Han108	101	NC	NC	
Arm Han108	102		95 ohm	
Arm Han108	103	VALVE1+	0	
Arm Han108	104		95 ohm	
Arm Han108	105	NC	NC	
Arm Han108	106		21 ohm all	JT6 U
Arm Han108	107	JT6 U		JT6 V
Arm Han108	108			JT6 W