

Print at actual size and use to find the right angles where holes should be drilled (current holes are marked)