
Sean Lai, ME120 Section 001, PWM Calibration (USB Power)

Homework #5 Problem 1, due 11/25/19.

Motor B USB					
					Omega
PWM	# Turns (1)	# Turns (2)	# Turns (3)	Avg. Turns	(rad/s)
55	6.1	6	6.1	6.1	3.8
80	9.25	9.4	9.5	9.4	5.9
105	12.3	12.7	12.6	12.5	7.9
130	16.25	16.25	16.25	16.3	10.2
155	19.75	19.8	19.8	19.8	12.4



Equation of fit line:

 $y = -0.112x^2 + 13.415x + 5.378$