



Synthetic prototype — not for operational use

POWERPLANTS ONE · SERVICE OPERATIONS

Customer service report

SYN-PPO-RPT-000018 · r01

SYN Greenhouse Demonstration · SYN Q01 Demonstration Site

Work SYN-PPO-WO-000010 · Visit SYN-PPO-APT-000033

Prepared for SYN Avery Contact

Reserved output preparation 2026-10-02T06:57:07.468Z · Issue db0293af-7832-4c2e-a101-7de72d14df4d. Release requires the application's separate immutable issue event. This file alone does not prove release or delivery.

Attendance and scope

SYN Riley Technician · 2 Oct 2026, 4:56 pm to 2 Oct 2026, 4:56 pm (Australia/Brisbane)

Attendance acceptance is separate from remaining work, customer response and financial treatment.

SYN Planned controller inspection — coordination and customer date review

Authorised exclusions: No shutdown, replacement, energised access, repair or financial approval.

Scope outcome: Partial

Authority review: Current. Original-attendance-only review gives no further work authority.

Equipment and identity

Equipment	Identity
SYN irrigation controller	Verified

Partial · SYN visual inspection attempted; identity remains uncertain.

[illegible]

Findings, attempted fixes and evidence

SYN visual observation only

Result

SYN no repair or technical clearance

Follow up required

Yes

Exclusions and remaining work

SYN no intervention, no whole-project acceptance and no financial treatment.

SYN second task requires a separately authorised return. Service coordinator owns identification and contact.

Unresolved finding requires follow-up.

An authorised task remains incomplete.

A task result has not passed the synthetic completion check.

The synthetic site-controls completion check has not passed.

Next-action owner: Service coordinator. A proposed return requires separate confirmation and work authority.

Customer response context

A response describes only the exact content presented. It does not approve billing, the entire project, statutory compliance or warranty settlement. Stated identity and an optional synthetic mark are not independently verified identity. Responses are recorded separately; this PDF is never changed to add a signature.

Exact customer content 20c35c36243a130c3309308c0fcc0023e7753b7e1bbc8112f9cff9f95efc82d1

Template 6a77a93522e8cc96a542707ceccfd55fafa84f6cb0644e69b7660f826224238f · SYN-PPO-RPT-000018 r01. Findings retain their recorded confidence; uncertain findings are not established diagnoses.