

P1-S1 drawing revision. Four actuators remain external. Labels connect blocks; solid wires show each local circuit.

