Pinnen & adressen

I²C adressen:

US, front left: 0xE0 US, front right: 0xE2 US, rear left: 0xE4 US, rear right: 0xE6 compass: 0xC0

GPIO pinnen:

- 2: left, reverse
- 3: left, forward
- 4: left, enable
- 5: right, reverse
- 6: right, forward
- 7: right, enable
- 8: button & led 1 (*)
- 9: button & led 2 (*)
- (*) output = LED, imput = button