

				. (./	
Prepared (also subject responsible if other)		No.			
Rajasekar R					
Approved	Checked	Date	Rev	Reference	
		27-03-2020	Ver1.0		

MOP of Lag Member Down Alarm for Huawei Site

Table of contents

Activity Description	2
Flow Chart	3
Activity Details	
10, 20.0	



Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	


Activity Description

Alarm Name	1. LAG_MEMBER_DOWN	
Alarm Description	1. Link Aggregation Member Down	
Possible Causes	1. Aggregated Port down.	
	2. DXPIC hops any link got down	



Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	

Flow Chart





Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	

Activity Details

Aggregated Port Down:

- 1. If a POP have more dependency 1G port not sufficient to serve all dependent sites.
- 2. In those case 2nd port HO taken and it will be aggregated to share equal traffic for 2G.
- 3. Depend upon the requirement 3G & 4G aggregation to be done on both RTN & MUX end.

DXPIC Hops Link Down:

- 1. Requirement of More BW & More dependency DXPIC will be installed.
- 2. LAG will be working on HASH algorithm.