Behaviour of Cards Under Multicast

This is how they currently behave, not what the hardware can do—for example, the Lance driver doesn't use its filter, even though the code for loading it is in the DEC Lance—based driver.

The following are requirements for multicasting

AppleTalk	Multicast	hardware filtering not important but avoid cards only doing promisc hardware filters really help hardware filters are of no help		
IP-Multicast IP-MRoute	Multicast AllMulti			
Board	Multicast	AllMulti	Promisc	Filter
3c501 3c503 3c505 3c507 3c509 3c59x ac3200 apricot arcnet at1700 atp cs89x0 de4x5 de600 de620 depca dmfe e2100 eepro eexpress ewrk3 hp-plus hp hp100 ibmtr ioc3-eth lance ne ni52 ni65 seeq sgiseek	YES YES YES NO YES YES YES YES YES NO PROMISC PROMISC YES YES NO PROMISC YES YES NO PROMISC YES	YES YES NO NO NO YES YES YES YES PROMISC NO PROMISC PROMISC YES YES NO PROMISC PROMISC YES YES YES PROMISC YES YES YES PROMISC YES YES PROMISC YES YES PROMISC NO PROMISC YES YES PROMISC NO PROMISC YES YES NO YES NO YES NO YES NO YES NO YES NO YES YES NO YES	YES YES YES NO YES YES YES YES NO YES	Software Hardware N/A Software Hardware Hardware Hardware Hardware Software Software Hardware Ho/A Hardware Software(#) Hardware Hardware Hardware
smc-ultra sunlance tulip wavelan wd xirc2ps_cs znet	YES YES YES YES YES YES YES	YES YES YES PROMISC YES YES YES YES	YES YES YES YES YES YES YES YES YES	Hardware Hardware Hardware Hardware Hardware Hardware Software

第 1 页

multicast.txt

PROMISC = This multicast mode is in fact promiscuous mode. Avoid using cards who go PROMISC on any multicast in a multicast kernel.

- (#) = Hardware multicast support is not used yet.
 (*) = Hardware support for Davicom 9132 chipset only.