## VIA82xx-mixer.txt

## VIA82xx mixer

On many VIA82xx boards, the 'Input Source Select' mixer control does not work. Setting it to 'Input2' on such boards will cause recording to hang, or fail with EIO (input/output error) via OSS emulation. This control should be left at 'Input1' for such cards.