```
#        File : subevent.conf

######################## Subscribe Events command #################
subevent_get={
        CmdCode=0x0075  # do NOT change this line

        Action:2=0              # GET
        Events:2=0
}

subevent_set={
        CmdCode=0x0075  # do NOT change this line

        Action:2=1              # SET
        Events:2=0xbc8  # bit0 - Beacon RSSI_LOW; bit1 - Beacon SNR_LOW
                                # bit2 - FAILED_COUNT; bit3 - Beacon
Missed
                                # bit4 - Beacon RSSI_HIGH; bit5 - Beacon
SNR_HIGH
                                # bit6 - Data RSSI_LOW; bit7 - Data
SNR_LOW
                                # bit8 - Data RSSI_HIGH; bit9 - Data
SNR_HIGH
                                # bit10 - LINK_QUALITY; bit11 -
PRE_BCN_LOST
                                # bit12-15 reserved

        LowRssiTlvType:2=0x0104
        LowRssiTlvLength:2={
                Threshold:1=70
                ReportingFreq:1=0
        }

        LowSnrTlvType:2=0x0105
        LowSnrTlvLength:2={
                Threshold:1=56
                ReportingFreq:1=0
        }

        FailedCountTlvType:2=0x0106
        FailedCountTlvLength:2={
                Threshold:1=5
                ReportingFreq:1=0
        }

        BeaconMissTlvType:2=0x0107
        BeaconMissTlvLength:2={
                BeaconMissed:1=60
                Reserved:1=0
        }

        HighRssiTlvType:2=0x0116
        HighRssiTlvLength:2={
                Threshold:1=40
                ReportingFreq:1=0
        }
```

```
HighSnrTlvType:2=0x0117
HighSnrTlvLength:2={
        Threshold:1=86
        ReportingFreq:1=0
}

DataLowRssiTlvType:2=0x0126
DataLowRssiTlvLength:2={
        Threshold:1=10
        ReportingFreq:1=0
}

DataLowSnrTlvType:2=0x0127
DataLowSnrTlvLength:2={
        Threshold:1=66
        ReportingFreq:1=0
}

DataHighRssiTlvType:2=0x0128
DataHighRssiTlvLength:2={
        Threshold:1=50
        ReportingFreq:1=0
}

DataHighSnrTlvType:2=0x0129
DataHighSnrTlvLength:2={
        Threshold:1=96
        ReportingFreq:1=1
}
LinkQualityTlvType:2=0x0124
LinkQualityTlvType:2={
        LinkSNRThreshold:2=0x0056
        LinkSNRFrequency:2=0x0003
        MinRateVal:2=0x0014
        MinRateFreq:2=0x0003
        TxLatencyVal:4=0x00C8
        TxLatencyThreshold:4=0x0003
}
PreBcnLostTlvType:2=0x0149
PreBcnLostTlvLength:2={
        PreBeaconCnt:1=30
        Reserved:1=0
}
}
######################### Subscribe Events command #################
```