Lab Assignment 2

```
Test Cases:
1. INPUT: F1 = 1
        Ascending = 1
        B2 = 1
        B0 = 1
        UP2 = 1
      and rest all = 0
OUTPUT:
        Go_up=1
2. INPUT : F1 = 1
      Descending = 1
      B2 = 1
      B0 = 1
      UP2 = 1
      and rest all = 0
OUTPUT:
      Go_down = 1
3. INPUT: F2 = 1
          Descending = 1
          DN1 = 1
          UP2 = 1
          and rest all = 0
OUTPUT:
      Go_down=1
SCHEMATIC:
Explained in lab assignment 1 report.
CONSTRAINT FILE:
In Basys 3 board;
   Inputs assigned:
V17 = Ascending
V16 = B0
W16 = B1
W17 = B2
W15 = B3
V15 = Descending
W14 = UP0
W13 = UP1
V2 = UP2
T3 = DN1
T2 = DN2
R3 = DN3
```

W2 = F0

U1 = F1 T1 = F2

R2 = F3

Outputs assigned:

U16 = Go_down E19 = Go_up

Manoj Kumar 2018CS50411 Nikita Bhamu 2018CS50413