

MARUTI SERVICE CENTER

Workshop Code :000049

NH-14, Tilai, Beside Atithi Family Restaurant, Rampurhat-1, Birbhum,
West Bengal - 731224

GSTIN: NA

Repair Report

Complaints Schedule Service 1-Schedule Service 1 :	Jobcard No: NJ0000492526-90	Breakdown Id: 20250617003203
	Repair Report No: NI0000492526-91	Repair Report Date:25-06-2025 17:02:19
	In Date: 25-06-2025 16:03:51	
Vehicle Number : WB23E0956 In Odo Reading : 390882 Out Odo Reading : 0 Phone Number : 9153230050 Email : sanjoykrk91@gmail.com Off Road Time : 25-06-2025 13:31:33	EME Name :Saikat Dutta EME Contact No :7872484583 Address : MD. BAZAR BPHC District: : BIRBHUM	Project: : 102 Final Approver: : Srikanta Dutta

Services

#	Service Number	Service Description	Remarks	Repetition Remarks	Qty	Service Total	Labour Total	Total Cost
1	30433	SPECIAL SERVICES	Mandatory Service	Service charges for changing oil, air, diesel filters, engine oil, gear oil	1	250.00	0	250.00
							Grand Total :	250.00

Repeated Parts/Services

S.No	Line Item	Type	Life Span	Workshop Name	Breakdown Id	Jobcard Number
1	SPECIAL SERVICES	S	120	MARUTI SERVICE CENTER	20250317001246	NJ0000492425-361

Grand Total

Parts Total : 0.00
Service Total: 250.00
Grand Total : 250.00

Amount (in Words): INR Two Hundred Fifty rupees Only

Pending Jobs :

Observation : Ok, for operations

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

This is a system-generated document. Does not require any signature

Authorized Signature

MARUTI SERVICE CENTER

Print Date :25-06-2025 17:02:00