


**MEBA**  
sawing solutions.



# **MEBA** **BANDSAW** **BLADES**

WE BUILD TO CUT YOUR COST




## MEBA Bi-Metal P

M42

Non-ferrous metals-Aluminum, copper, brass.  
Structural steel-columns, angles, I beam.  
Steels-Low & medium carbon steel.

ADVANTAGES : General Purpose Grade

- AREAS OF APPLICATION :  SOLID MATERIAL  SOLID BUNDLE
- PRODUCT FEATURES :  STANDARD TOOTH
- PRODUCT ADVANTAGES :  UNIVERSALLY APPLICABLE




## MEBA Bi-Metal S

M42

Non-ferrous metals-Aluminum, copper, brass.  
Structural steel-columns, angles, I beam.  
Steels-Low & medium carbon steel.

ADVANTAGES : Increase Cutting Accuracy and Wearability

- AREAS OF APPLICATION :  SOLID MATERIAL  SOLID BUNDLE
- PRODUCT FEATURES :  STANDARD TOOTH
- PRODUCT ADVANTAGES :  UNIVERSALLY APPLICABLE



## MEBA Bi-Metal E Plus

M42

Structural steel-columns, angles, C channel, I beam.  
Steels-Alloy steels, low & medium carbon steel.

ADVANTAGES : For profiles and bundle cuts.  
For small and often changing  
workpiece dimensions

- AREAS OF APPLICATION :  TUBES AND PROFILES  SOLID BUNDLE
- PRODUCT FEATURES :  HOOK TOOTH
- PRODUCT ADVANTAGES :  COST REDUCTION  UNIVERSALLY APPLICABLE




## MEBA Bi-Metal H1

M42

Ferrous & Non-Ferrous metals-Aluminum, copper, brass, steel. Steels-Alloy steels, high carbon steel

ADVANTAGES : General Purpose Grade

- AREAS OF APPLICATION :  SOLID MATERIAL  BEAMS  SOLID BUNDLE
- PRODUCT FEATURES :  STANDARD TOOTH
- PRODUCT ADVANTAGES :  UNIVERSALLY APPLICABLE



## MEBA Bi-Metal PB

M42


Structural steel-columns, angles, C channel, I beam.  
Steels-Alloy steels, low & medium carbon steel.

**ADVANTAGES :** High tool life at cutting of hollow  
Sections & bad supported I-beam  
for bundle cuts, H-beams

**AREAS OF APPLICATION :**  BEAMS  TUBES & PROFILES

**PRODUCT FEATURES :**  REINFORCED HOOK TOOTH  SETTING

**PRODUCT ADVANTAGES :**  VIBRATION & NOISE REDUCTION  WEAR RESISTANCE  COST REDUCTION



## MEBA Bi-Metal H1-HL

M42


Ferrous & Non-Ferrous metals-Aluminum, copper,  
Titanium, steel. Cast Iron-Grey cast iron  
wrought iron Steels-Alloy steels, high carbon steel.

**ADVANTAGES :** Specially developed positive tooth  
Profile for sawing more easily with  
Reduced feed force

**AREAS OF APPLICATION :**  SOLID MATERIAL  SOLID BUNDLE

**PRODUCT FEATURES :**  GROUNDED TOOTH

**PRODUCT ADVANTAGES :**  PERFORMANCE  PRECISION  COST REDUCTION



## MEBA Bi-Metal H2

M51


Ferrous & Non-Ferrous metals-Aluminum, copper,  
titanium, steel. Cast iron-grey cast iron, white cast iron,  
wrought iron Steels-Alloy steels, high carbon steel.

**ADVANTAGES :** General Purpose Grade

**AREAS OF APPLICATION :**  SOLID MATERIAL  SOLID BUNDLE

**PRODUCT FEATURES :**  STANDARD TOOTH

**PRODUCT ADVANTAGES :**  PERFORMANCE  WEAR RESISTANCE  COST REDUCTION



## MEBA Bi-Metal H2-HL

M51

Ferrous metals-Chromium, nickel, titanium, steel.  
Steels-Alloy steels, low-medium & high carbon steel.

**ADVANTAGES :** High tool life at cutting of hollow  
Sections & bad supported I-beam  
for bundle cuts, H-beams

**AREAS OF APPLICATION :**  SOLID MATERIAL  SOLID BUNDLE

**PRODUCT FEATURES :**  GROUNDED TOOTH

**PRODUCT ADVANTAGES :**  PERFORMANCE  WEAR RESISTANCE  COST REDUCTION





## **BANDSAW MACHINES- ROUTINE CHECKS**

Check Regularly:

- Proper Working Of Chip Brush
- Coolant Level And Correct Concentration
- Alignment And Wear Condition Of Blade Guides
- Blade Tension (As Per Specification)
- Blade Cutting Speed



## **COOLANT / CUTTING FLUID**

Coolant Helps In Cooling And Chip Removal During Cutting.

Important Points:


- Use Cutting Fluid Suitable For The Specific Application
- Maintain Recommended Concentration Level



## **WORKPIECE HANDLING**

Important Points:

- Ensure The Workpiece Is Firmly Clamped (No Vibration Or Movement)
- Avoid Using Band Damaged Or Deformed Materials
- Keep Blade Guide As Close As Possible To The Workpiece For Better Accuracy



## **START-UP GUIDELINES**

Important Points:

- Follow Proper Start-up Procedure
- Use Recommended Cutting Parameter For Longer Blade Life

# **RECOMMENDED TEETH PER INCH (TPI) FOR BANDSAW BLADES**

## **Teeth Per Inch For Solid Material**

| Cutting in (mm) | TEETH PER INCH (TPI) |      |      |     |     |     |     |       |
|-----------------|----------------------|------|------|-----|-----|-----|-----|-------|
|                 | 10/14                | 8/12 | 6/10 | 5/8 | 4/6 | 3/4 | 2/3 | 1 1/2 |
| 0-20            | ■                    |      |      |     |     |     |     |       |
| 20-50           |                      | ■    |      |     |     |     |     |       |
| 25-60           |                      |      | ■    |     |     |     |     |       |
| 35-80           |                      |      |      | ■   |     |     |     |       |
| 50-100          |                      |      |      |     | ■   |     |     |       |
| 80-150          |                      |      |      |     |     | ■   |     |       |
| 120-350         |                      |      |      |     |     |     | ■   |       |
| 250-600         |                      |      |      |     |     |     |     | ■     |

## **Teeth Per Inch For Angle / Channel / Pipe**

| D (mm)<br>S (mm) | TEETH PER INCH (TPI) |       |       |       |       |       |       |       |       |
|------------------|----------------------|-------|-------|-------|-------|-------|-------|-------|-------|
|                  | 20                   | 40    | 60    | 80    | 100   | 150   | 200   | 300   | 500   |
| 2                | 10/14                | 10/14 | 10/14 | 10/14 | 10/14 | 10/14 | 10/14 | 10/14 | 8/12  |
| 3                | 10/14                | 10/14 | 10/14 | 8/12  | 8/12  | 8/12  | 6/10  | 6/10  | 6/10  |
| 4                | 10/14                | 10/14 | 10/14 | 8/12  | 8/12  | 6/10  | 6/10  | 5/8   | 4/6   |
| 5                | 10/14                | 10/14 | 10/14 | 8/12  | 6/10  | 6/10  | 5/8   | 4/6   | 4/6   |
| 6                | 10/14                | 10/14 | 8/12  | 8/12  | 6/10  | 5/8   | 5/8   | 4/6   | 4/6   |
| 8                | 10/14                | 8/12  | 6/10  | 6/10  | 6/10  | 5/8   | 5/8   | 4/6   | 4/6   |
| 10               |                      | 6/10  | 6/10  | 5/8   | 5/8   | 4/6   | 4/6   | 4/6   | 3/4   |
| 12               |                      | 6/10  | 5/8   | 4/6   | 4/6   | 4/6   | 4/6   | 3/4   | 3/4   |
| 15               |                      |       |       | 4/6   | 4/6   | 3/4   | 3/4   | 3/4   | 2/3   |
| 20               |                      |       |       | 4/6   | 4/6   | 3/4   | 3/4   | 3/4   | 2/3   |
| 30               |                      |       |       | 3/4   | 3/4   | 3/4   | 2/3   | 2/3   | 2/3   |
| 50               |                      |       |       |       |       | 2/3   | 2/3   | 2/3   | 1 1/2 |
| 75               |                      |       |       |       |       |       | 2/3   | 1 1/2 | 1 1/2 |
| 100              |                      |       |       |       |       |       |       | 1 1/2 | 1 1/2 |

When you clamp 2 or more tubes placed side by side, use above list with the double wall thickness (S).

**MEBA**  
sawing solutions.



+91-86850-00843



info@mebaindia.com



www.mebaindia.com



Plot No-160 ,DLF Industrial Estate,Phase-1, Village Atmadpur, Faridabad-121003